

Mahaska County SLF visit 7/2/19



entrance road



north slope leachate seepage



north slope leachate seepage



appliance storage area



north slope leachate seepage



north slope leachate seepage



Cell 2 working area facing SE



north slope leachate seepage



north slope leachate seepage



Cell 2 working area facing SW



north slope leachate seepage



north slope leachate seepage



north slope leachate seepage



north slope leachate seepage



north slope leachate seepage

Mahaska County SLF visit 7/2/19



west slope leachate seepage



west slope leachate seepage



Cell 3



Cell 3 foreground; Cell 2 background