## SCS ENGINEERS

April 29, 2025 File No. 27225033.00

Mr. Mick Leat Iowa Department of Natural Resources Land Quality Bureau 6200 Park Avenue Des Moines, Iowa 50321

Subject: Spring 2025 Semiannual Inspection Report

ADM Clinton Landfill (Closed) Permit No. 23-SDP-05-88C

Dear Mick,

This brief report documents the semi-annual inspection required by the facility's lowa Department of Natural Resources (DNR) Sanitary Disposal Project Permit and the lowa Administrative Code. The inspection was made to evaluate the site's general conformance with the permit and the approved plans and specifications. A site map is attached for reference (Figure 1). A copy of the observation checklist used during the inspection is included in Attachment A. A summary from the inspection is provided below.

#### SUMMARY OF INSPECTION OBSERVATIONS

The following items were observed:

- Landfill cover and vegetation on the side slopes and cap area were well established.
- No areas of erosion were observed.
- No areas of ponding on the landfill cap were observed.
- No leachate seeps were observed.

#### SUMMARY OF NON-CONFORMANCE WITH PERMIT CONDITIONS

No items of non-conformance were observed during the inspection.

Items not considered non-compliance but should continue to be monitored included the following:

- Continue to monitor and maintain the landfill cap as necessary.
- Stormwater control structures should continue to be monitored and sediments removed as necessary to allow for free flow of stormwater off the landfill cap.



Mick Leat April 29, 2025 Page 2

If you have any questions about this report, please contact us as noted below.

Sincerely,

Semir Omerovic Technical Associate SCS Engineers

somerovic@scsengineers.com

(515) 988-3237

SO/KAJ/CLC

cc: Bobby Peropat - Archer Daniels Midland Company

Iowa DNR Field Office #6

#### Certification

misting L Collier


Christine L. Collier, P.E.

Senior Project Manager

ccollier@scsengineers.com

**SCS** Engineers

(515) 631-6161



Encl. Figure 1 - Site Map Attachment A - Sanitary Landfill Inspection Checklist





# Site Map

## Legend

Approximate Monitoring Well Location

A HMSP Monitoring Well Location Approximate Location of Extraction Well

Approximate Location of Leachate Piezometer Approximate Waste Boundary

Approximate Property Boundary

**ADM Clinton Landfill** Clinton, Iowa Project No: 27225033.00 Drawing Date: April 2025




Figure 1

## ATTACHMENT A SANITARY LANDFILL INSPECTION CHECKLIST

SCS Engineers 1690 All-State Court, Suite 100			
Sanitary Landfill Inspection Checklist			
Permit #: 23-SDP-05-88C			
Facility Name: ADM Clinton Landfill	Responsible Official: Eric Fasnacht		
County: Clinton	Address: 1251 Beaver Channel Parkway, Clinton, Iowa		
Facility Operator: Archer Daniels Midland Company	Phone: (314) 872-2406		
Address: 1251 Beaver Channel Parkway, Clinton, Iowa	Date Last Inspection: October 9, 2024		
Phone: (563) 242-1121	Date This Inspection: March 19, 2025		
At the Time of this Inspection:			
Facility personnel present: None	Surface conditions:     Damp, raining		
Wind direction and speed: Northeast, 10-15 mph	Ambient temperature: 50° F		
Yes – compliance was being achieved; No – compliance was not being achieved, N/A – not applicable or not observed; PND – previously noted deficiency (PND). Observations			
Yes No N/A PND Item	Yes No N/A PND Item		
□ □ □ 1. Fill Cover: final	☐ ☐ ☐ ☐ 10. Special Waste Handling		
☐ ☐ ☐ 2. Control of Face	☐ ☐ ☐ ☐ 11. Recycling Activities		
☐ ☐ ☐ 3. Compaction	☐ ☐ ☐ ☐ 12. Operator Certification		
☐ ☐ 4. Cover erosion; Ponding	☐ ☐ ☐ 13. Staffing		
☐ ☐ ☐ 5. Drainage into fill	☐ ☐ ☐ 14. Equipment		
	Backup/Maintenance		
☐ ☐ 6. Leachate Mgmt. & Control	□ □ 15. Interior Roads		
☐ ☐ ☐ 7. Litter	☐ ☐ 16. Perimeter fence, gate, signs, wells		
8. Wet Weather Area	Tr. Photos taken		
9. Construction & Demolition Area	☐ ☐ 18. Follow-up needed? (Yes/No)		
Comments: The comments below correspond to the numbered observation items listed above.			
<ol> <li>Landfill cover and vegetation on the side slopes and cap area were well established.</li> </ol>			
4. No areas of erosion were observed. No areas of ponding were observed on the landfill cap.			
6. No leachate seeps were observed.			
15. Access roads leading to the site and within the site were in good condition.			
16. The perimeter fence, gate, signs, and wells were in good condition.			
18. The landfill cap should continue to be periodically monitored and maintained as needed. Stormwater control structures should			

18. The landfill cap should continue to be periodically monitored and maintained as needed. Stormwater control structures should continue to be monitored and sediments removed as necessary to allow for free flow of stormwater off the landfill cap.

AUTHENTICATION		
INSPECTOR	Kevin Jensen and Semir Omerovic	Date: 3/19/2025
REVIEWER	Christine L. Collier, P.E.	Date: 4/17/2025