SCS ENGINEERS

April 29, 2025 File No. 27225231.00

Mr. Mick Leat lowa Department of Natural Resources Land Quality Bureau 6200 Park Avenue Suite 200 Des Moines, Iowa 50321

Subject: 2025 Biennial Inspection Report

Tama Paperboard Landfill Permit No. 86-SDP-03-91C

Dear Mick,

This brief report documents the biennial inspection required by the facility's lowa Solid Waste Program Environmental Covenant recorded January 31, 2024 (Doc # 109086). The inspection was made to evaluate the site's general conformance with the activity and use limitations and terms listed in the environmental covenant and applicable requirements. A site map is attached for reference (Figure 1). A copy of the observation checklist used during the inspection is included in Attachment A. A summary of the inspection is provided below.

SUMMARY OF INSPECTION OBSERVATIONS

The following items were observed:

- Cap vegetation was well established and had been mowed on the north portion of the cap. No areas of sparse vegetation were observed.
- No areas of erosion were observed
- No areas of ponding were observed.
- No leachate seeps were observed.
- No violations of the activity and use limitations and terms described in the environmental covenant were observed.

SUMMARY OF NON-CONFORMANCE WITH PERMIT CONDITIONS

There were no items of non-conformance observed during the inspection.

Items not considered non-compliance but should continue to be monitored included the following:

• Continue to periodically monitor the landfill for signs of erosion and loss of vegetation and maintain as needed.



Mick Leat April 29, 2025 Page 2

If you have any questions about this report, please contact us as noted below.

Sincerely,

Kevin Jensen Project Manager SCS Engineers

kjensen@scsengineers.com

515-368-3155

SO/KAJ/CLC

cc: Jill Apfel, Tama City Clerk


Christine L. Collier, P.E. Senior Project Manager SCS Engineers

ccollier@scsengineers.com


misting L Collier

515-418-0677

Certification



Encl. Figure 1 – Site Map
Attachment A – Sanitary Landfill Inspection Checklist





SCALE



NOTE: CONTOURS GENERATED FROM TRACING HRG FIELD SURVEY DATA DATED SEPTEMBER, 1993 THAT WAS GENERATED BY HOWARD R. GREEN CO.

LEGEND

EXISTING GROUND SURFACE (1 FT. CONTOUR INTERVAL)

- APPROXIMATE WASTE BOUNDARY

APPROXIMATE WASTE BOUNDARY
OF PRE-1970 REFUSE FILL
AREA

- --- x -- FENCELINE

TAMA PAPERBOARD LANDFILL TAMA, IOWA PROJECT NO. 27225231.00 DRAWING DATE: APRIL 2025 **SCS** ENGINEERS

FIGURE

1

ATTACHMENT A SANITARY LANDFILL INSPECTION CHECKLIST

SCS Engineers 1690 All-State Court, Suite 100 Sanitary Landfill Inspection Checklist	
Permit #: 86-SDP-03-91C	
Facility Name: Tama Paperboard Landfill	Responsible Official: Brian Hanus, Mayor
County: Tama	Address: 305 Siegel Street, Tama, IA
Facility Operator: City of Tama	Phone: (641) 484-3822
Address: 305 Siegel Street, Tama, Iowa	Date Last Inspection: August 22, 2022
Phone: (641) 484-3822	Date This Inspection: April 1, 2025
At the Time of this Inspection:	
Facility personnel present: None	Surface conditions: Damp
Wind direction and speed: South, 20-25 mph	Ambient temperature: 42° F
Yes – compliance was being achieved; No – compliance was not being achieved, N/A – not applicable or not observed; PND – previously noted deficiency (PND).	
Observations	
Yes No N/A PND Item	Yes No N/A PND Item
□ □ 1. Fill Cover: final	☐ ☐ ☐ ☐ 10. Special Waste Handling
	☐ ☐ ☐ ☐ 11. Recycling Activities
3. Compaction	☐ ☐ ☐ 12. Operator Certification
□ □ 4. Cover erosion; Ponding	☐ ☐ ☐ 13. Staffing
□ □ □ 5. Drainage into fill	☐ ☐ ☐ 14. Equipment
6. Leachate Mgmt. & Control	Backup/Maintenance 15. Interior Roads
7. Litter	15. Interior roads 16. Perimeter fence, gate, signs,
	wells
S. Wet Weather Area	☐ ☐ ☐ ☐ 17. Photos taken
☐ ☐ ☑ ☐ 9. Construction & Demolition Area	☐ ☐ ☐ 18. Follow-up needed? (Yes/No)
Comments: The comments below correspond to the numbered observation items listed above.	
1. Landfill cover and vegetation on the landfill cap was well established.	
No areas of erosion were observed. No areas of ponding were observed on the landfill cap.	
6. No seeps were observed.	
18. The landfill cap should continue to be periodically monitored and maintained as needed.	
AUTHENTICATION	
AUTHENT	ICATION
INSPECTOR Kevin Jensen and Semir Omerovic	Date: 4/1/2025
REVIEWER Christine L. Collier, P.E.	Date: 4/17/2025