

April 25, 2019

Mr. Michael Smith, P.E.
Iowa Department of Natural Resources
Land Quality Bureau
Wallace State Office Building
502 East 9th Street
Des Moines, Iowa 50319-0034

Re: Monthly Inspection Report for Sac County Landfill Closure

(November 2018 through April 2019)

Sac County Sanitary Landfill Permit No. 81-SDP-01-75 Project No. SACSW 19001

Dear Mike:

This report documents the monthly inspections required by the facility's Iowa Department of Natural Resources Sanitary Disposal Project Closure Permit and the Iowa Administrative Code. The inspections were made to evaluate the site's general conformance with the closure permit and the approved plans and specifications. A map of the municipal solid waste landfill (MSWLF) unit is attached for reference (Figure 1). Copies of the inspection checklist used during the inspections are included in Attachment A.

Monthly inspections of the site are required after substantial completion of the final cover construction project for Cells 5 through 7C, which occurred on June 6, 2018. Inspections of the closure cap were completed on November 15, 2018, December 13, 2018, February 14, 2019, March 21, 2019, and April 9, 2019. It should be noted that it was approved in email correspondence dated January 25, 2019 to not complete the January 2019 inspection due to snow cover. The following was noted during the monthly inspections.

Summary of Inspection Observations

- Final grading and seeding have been completed and substantial completion of the final cover occurred on June 6, 2018.
- Terraces along the north side of Cells 7A, 7B, and 7C exhibited erosion due to lack of vegetation
 and overtopping due to excessive sediment. The contractor that performed the closure
 construction project regraded the terraces, removed the sediment, and re-seeded the bare areas
 on October 23, 2018. Vegetation has not established at this time. Landfill personnel are
 coordinating with the contractor for additional seeding of the bare areas.
- Turf reinforcement matting was not installed correctly in Letdown A and erosion along the letdown was evident. The contractor that performed the closure construction project installed additional turf reinforcement mat in Letdown A as well as the terraces that discharge into Letdown A on October 23, 2018. Erosion was still present along Letdown A. Further repairs are necessary.





Summary of Non-Conformance with Permit Conditions

No items of non-conformance were noted during the inspections. Items not considered non-conformance, but should continue to be monitored included the following:

- It is recommended to implement a routine mowing and tree removal program to control deep rooted vegetation.
- It is recommended that landfill personnel continue to remove accumulated sediment from the terraces and letdowns and re-seed bare spots as necessary.

General Comments

The observations presented in this report are based upon data obtained from the field observations made at the site, interviews with the site operator, and from information sources discussed in this report. This report provides a snapshot in time of the conditions present at the time of the inspection and does not reflect variations in conditions that may occur throughout the year.

BARKER LEMAR has prepared this report for the exclusive use of our client. This report is meant for the specific application discussed and has been prepared in accordance with generally accepted engineering practices. No warranties, expressly stated or implied, are intended or made.

If you have any questions regarding this report, please contact us at (515) 256-8814.

Sincerely,

BARKER LEMAR ENGINEERING CONSULTANTS

Lauren P. Norland, P.E.

Project Engineer

David G. Phillips, P.E.

Design Engineer

cc:


Addressee

Mr. Jim Wissler, Sac County Solid Waste Agency Mr. Cliff Frohardt, Sac County Sanitary Landfill

Electronic File

Engineer's Certification

I hereby certify that this engineering document was prepared by me personal supervision and that I am a duly licensed Professional Engine the State of Iowa. LAUREN PAIGE NORLAND P25064 My license renewal date is December 31, 2019. Pages or sheets covered by this seal: All.	
---	--



ATTACHMENT A OBSERVATION CHECKLIST

Sanitary Landfill Inspection - Closed Facility								
81-SDP-	01-75 Date this Inspection:	11/15/2018		Previous Inspection Date:		10/23/2018		
Sac Cou	inty Sanitary Landfill Weather	Condition at Tim	e of Visi	t: 50° F, S un	nγ			
ontacted:	JB Huster							
						oted Deficiency		
PND	Item	Yes	No	PND	ltem			
) 🗆	1. Fill Cover: daily; intermediate; final				10. Special Waste H	andling		
	2. Control of Face: slope; width; location				11. Recycling Activit	ties		
	3. Compaction				12. Operator Certifi	cation		
) 0	4. Cover erosion; Ponding		Ø		13. Staffing			
) 🗆	5. Drainage into fill				14. Equipment Back	up/Maintenance		
1 🗆	6. Leachate Mgmt. & Control		Ø		15. Interior Roads			
) 🗆	7. Litter		Ø		16. Perimeter fence	, gate, signs, mon. wells		
	8. Wet Weather Area	Ø			17. Photos taken			
) 🗆	9. Construction & Demolition Area	Ø			18. Follow-up need	ed		
Comments: Required Activities: 4. Erosion/rutting of erosion layer was repaired and re-seeded by closure construction Contractor in October 2018. Bare areas and areas of erosion are still present. These areas should be monitored and reseeded, if necessary. General Comments: Closure project Contractor repaired erosion, installed turf reinforcement mat, and re-seeded bare spots in October 2018. These areas should continue to be monitored								
Inspector Lauren Norland 11/16/2018 Printed Name Date Communication of the Signature Description of th								
	Sac Coulontacted: Yes PND PND Coulontacted: Yes PND Coulontacted: PND Coulontacted: PND Coulontacted: PND Coulontacted: Coulontac	81-SDP-01-75 Sac County Sanitary Landfill Weather ontacted: JB Huster Were deficiencies noted or s Yes - See Comments Sec., No - No deficiencies not PND Item 1. Fill Cover: daily; intermediate; final 2. Control of Face: slope; width; location 3. Compaction 4. Cover erosion; Ponding 5. Drainage into fill 6. Leachate Mgmt. & Control 7. Litter 8. Wet Weather Area 9. Construction & Demolition Area citivities: utting of erosion layer was repaired and re-seeded by clothese areas should be monitored and reseeded, if necessing iect Contractor repaired erosion, installed turf reinforcements:	Sac County Sanitary Landfill Weather Condition at Time Intacted: JB Huster Were deficiencies noted or significant observation in the Condition of Time Intacted: JB Huster Were deficiencies noted or significant observation in the Condition of Secretarion in the Condition of Secretarion in the Condition in the	81-SDP-01-75 Date this Inspection: 11/15/2018 Sac County Sanitary Landfill Weather Condition at Time of Visiontacted: JB Huster Were deficiencies noted or significant observations may be seen the condition of	81-SDP-01-75 Date this Inspection: 11/15/2018 Previous I Sac County Sanitary Landfill Weather Condition at Time of Visit: 50° F, Sun ontacted: JB Huster Were deficiencies noted or significant observations made during to the visit of visit of the visit of visit of the visit o	Sat County Sanitary Landfill Weather Condition at Time of Visit: 50° F, Sunny Intacted: JB Huster Were deficiencies noted or significant observations made during this inspection? Yes - See Comments Sec., No - No deficiencies noted, Blank - Not applicable or observed, PND - Previously Note Observations PND Item Yes No PND Item 1. Fill Cover: daily; intermediate; final 10. Special Waste H 2. Control of Face: slope; width; location 11. Recycling Activit 3. Compaction 12. Operator Certifit 4. Cover erosion; Ponding 2 13. Staffing 5. Drainage into fill 14. Equipment Back 6. Leachate Mgmt. & Control 2 15. Interior Roads 7. Litter 2 16. Perimeter fence 8. Wet Weather Area 2 17. Photos taken 9. Construction & Demolition Area 2 18. Follow-up need: It witties: It witties: It witties: It witties: It witties: It contractor repaired erosion, installed turf reinforcement mat, and re-seeded bare spots in October 2018. Bare areas a chase areas should be monitored and reseeded, if necessary.		

.

			Sanitary L	andfili Inspection	- Closed	Facility	
Permit #: 81-SDP-01-75 Date this ins		01-75 Date this inspection:	12/13/2018		Previous	Inspection Date: 11/15/2018	
Facility	r:	Sac Cou	inty Sanitary Landfill Weather	Condition at Tim	e of Visit	: 35° F, Clo	udy
Person	(s) Con	tacted:	Site Representative				
		Yes	Were deficiencies noted or s - See Comments Sec., No - No deficiencies no		pplicable		
Yes_	No	PND	item	Yes	No	PND	ltem
	V		1. Fill Cover: daily; intermediate; final				10. Special Waste Handling
			2. Control of Face: slope; width; location				11. Recycling Activities
			3. Compaction				12. Operator Certification
Ø		Ø	4. Cover erosion; Ponding		v		13. Staffing
			5. Drainage into fill				14. Equipment Backup/Maintenance
	V		6. Leachate Mgmt. & Control		v		15. Interior Roads
	V		7. Litter		v		16. Perimeter fence, gate, signs, mon. wells
			8. Wet Weather Area	Ø			17. Photos taken
			9. Construction & Demolition Area	Ø			18. Follow-up needed
pres Genera	al Comm	ese area	s should be monitored and reseeded, if necess	sary.		· · · ·	ber 2018. Bare areas and areas of erosion are still October 2018. These areas should continue to be
nspec	tor		Norland	12/14/2018		-	
	<	Printed	wen Nath	Date	•		

.

Sanitary Landfill Inspection - Closed Facility								
Permit	#:	81-SDP-	01-75 Date this Inspection:	02/14/2019		Previous I	nspection Date:	12/13/2018
Facility	/ :	Sac Cou	nty Sanitary Landfill Weather	Condition at Tim	e of Visit	t: 27 F, Clou	dy	
Person	(s) Con	tacted:	Site Representative					
Were deficiencies noted or significant observations made during this inspection? Yes - See Comments Sec., No - No deficiencies noted, Blank - Not applicable or observed, PND - Previously Noted Deficiency								
		103	See comments see, no no democración no	Observatio		or observed	a, THE Treviously No	red beneferey
Yes	No	PND	Item	Yes	No	PND	Item	
	V		1. Fill Cover: daily; intermediate; final				10. Special Waste H	andling
			2. Control of Face: slope; width; location				11. Recycling Activit	ies
			3. Compaction				12. Operator Certific	cation
V		V	4. Cover erosion; Ponding		1		13. Staffing	
			5. Drainage into fill				14. Equipment Back	up/Maintenance
	V		6. Leachate Mgmt. & Control		V		15. Interior Roads	
	V		7. Litter		V		16. Perimeter fence	, gate, signs, mon. wells
			8. Wet Weather Area	V			17. Photos taken	
			9. Construction & Demolition Area	V			18. Follow-up neede	ed
Require 4. Eros	Comments: Required Activities: 4. Erosion/rutting of erosion layer was repaired and re-seeded by closure construction Contractor in October 2018. Bare areas and areas of erosion are still present. These areas should be monitored and reseeded, if necessary.							
Genera Closure monito	e projec		ctor repaired erosion, installed turf reinforcem	nent mat, and re-	seeded b	pare spots in	October 2018. These	areas should continue to be
Inspect	Con	Printed	nous North	02/14/2019 Date		_		

* * *

			Sanitary La	indfill Inspection	- Closed	l Facility		
Permit #: 81-SDP-01-75		81-SDP-	01-75 Date this Inspection:	03/21/2019		Previous Inspection Date:		02/14/2019
Facility: Sac County Sanitary Landfill Weather Condition at Time of Visit: 36 F, Sunny								
Person(s) Contacted: Site Representative								
Were deficiencies noted or significant observations made during this inspection? Yes - See Comments Sec., No - No deficiencies noted, Blank - Not applicable or observed, PND - Previously Noted Deficiency Observations						oted Deficiency		
Yes	No	PND	Item	Yes	No	PND	Item	
	V		1. Fill Cover: daily; intermediate; final				10. Special Waste H	andling
			2. Control of Face: slope; width; location				11. Recycling Activit	ties
			3. Compaction				12. Operator Certifi	cation
V		V	4. Cover erosion; Ponding		V		13. Staffing	
			5. Drainage into fill				14. Equipment Back	cup/Maintenance
	V		6. Leachate Mgmt. & Control		V		15. Interior Roads	
	V		7. Litter				16. Perimeter fence	e, gate, signs, mon. wells
			8. Wet Weather Area	~			17. Photos taken	
			9. Construction & Demolition Area	7			18. Follow-up need	ed
pres Genera	ion/rut ent. Th al Comr e projec	ting of er ese areas ments:	rosion layer was repaired and re-seeded by closs should be monitored and reseeded, as necess ctor repaired erosion, installed turf reinforcem	ary.				
Inspec	tor	Jeff Phi Printed	TVāme -	03/21/2019 Date		_		

· <u> </u>			Sanitary 1	andfill Inspection	ı - Closed	i Facility		
Permit #: 81-SDP-01-75		81-SDP-	01-75 Date this Inspection:	04/09/2019		Previous	Inspection Date: 03/21/2019	
Facility: Sac County Sanitary Landfill			inty Sanitary Landfill Weather	Weather Condition at Time of Visit: 55 F, Cloudy				
Person	ı(s) Con	tacted:	Site Representative				·	
		Yes	Were deficiencies noted or see Comments Sec., No - No deficiencies no	_	pplicable	_		
Yes	No	PND	Item	Yes	No	PND	Item	
	Ø		1. Fill Cover: daily; intermediate; final				10. Special Waste Handling	
			2. Control of Face: slope; width; location				11. Recycling Activities	
			3. Compaction				12. Operator Certification	
Ø		Ø	4. Cover erosion; Ponding		V		13. Staffing	
			5. Drainage into fill				14. Equipment Backup/Maintenance	
	V		6. Leachate Mgmt. & Control		Ø		15. Interior Roads	
	V		7. Litter		Ø		16. Perimeter fence, gate, signs, mon. wells	
			8. Wet Weather Area	7			17. Photos taken	
			9. Construction & Demolition Area	Ø			18. Follow-up needed	
4. Eros pres	ent. Th	ting of ei ese area	rosion layer was repaired and re-seeded by closs should be monitored and reseeded, as neces		n Contrac	tor in Octol	ber 2018. Bare areas and areas of erosion are still	
			ctor repaired erosion, installed turf reinforcer	ment mat, and re-	seeded b	are spots in	October 2018. These areas should continue to be	
							,	
	. <u> </u>				,		·	
Inspec	tor	Printed	awren Marke	04/09/2019 Date	•	-		