RECEIVED
SEP 15 2014
DNR FO6

Washington WWTP (9271001)
Lexington Blvd lift station by-pass report
09/09/2014

The lift station by-pass occurred on the following dates and times.

This by-pass was caused by heavy rain. 3.43" total.

September 9, 2014 around 8:40 p.m. high water alarm call out to Jason @ 461-0865.

Around 9:00 p.m. Jason got to the lift station. There was no by-pass at that time. Jason left the lift station and headed out to the WWTP. Around 10:25 p.m. Jason got back to the lift station and waste water was just starting to run out the top of the wet well. Only one (1) pump was pumping (other pump is out of service and needs to be replaced) and it couldn't keep up. No electrical or mechanical problems occurred.

Jason reported the by-pass to the IDNR Field Office #6 via phone around 8:40a.m. He talked to Paul Brandt. They discussed by-pass details at that time. Jason told Paul we planned to send a written report that would include the by-pass details. I checked the lift station around 11:50 a.m. on the 10th and the by-pass had ended. Jason called Paul around 1:30 p.m. on the 10th to report the by-pass had ended

A grab sample was collected around 9:31 a.m. on the 10th to be tested for CBOD5, TSS, NH3, fecal coliform, e-coli, pH, and settable solids. I will forward the test results to Paul when they become available.

By-pass flow total unknown.

Fred E. Doggett # 2218
Fred E Doggett
Washington WWTP Supt.
Thursday, September 11, 2014

Jason Whisler # 8168
Jason Whisler
Washington WWTP Operator
Thursday, September 11, 2014

Copies to:
City Hall file
WWTP file