



July 29, 2015

Alliant Energy—Ottumwa Generating Station
20775 Power Plant Road
Ottumwa, IA 52501



Mr. Mark Heiderscheit
Iowa Department of Natural Resources
Field Office #6
1023 W. Madison
Washington, IA 52353

Dear Mr. Heiderscheit:

This letter serves as our 30-day spill report for the diesel fuel spill that occurred here at the Ottumwa Generating Station on July 23, 2015.

Spill report number: 072315-MRH-1547.

a. The exact location of the hazardous condition.

The spill occurred at Alliant Energy—Ottumwa Generating Station at 20775 Power Plant Road, Ottumwa, IA 52501. The spill was west of the reagent prep building and on the north, west, and south main concrete driveways.

b. The time and date of onset or discovery of the hazardous condition.

The spill was discovered at 10:30 AM on July 23, 2015.

c. The name of the material, the manufacturer's name, and the volume of each material involved in the hazardous condition in addition to contaminants within the material if they by themselves could cause a hazardous condition.

The spilled material was diesel fuel. The diesel fuel was purchased at a local filling station. The estimated quantity spilled was 10-15 gallons.

d. The medium (land, water, or air) in which the hazardous condition occurred or exists.

The diesel was spilled on the land (gravel and concrete).

e. The name, address, and telephone number of the party responsible for the hazardous condition.

The party responsible for the hazardous condition is Nichol Toomire, Alliant Energy—Ottumwa Generating Station, 20775 Power Plant Road, Ottumwa, IA 52501, (641) 935-2903.

f. *The time and date of the verbal report to the department of the hazardous condition.*
The DNR Field Office #6 was called at 3:48 PM on 07/23/2015.

g. *The weather conditions at the time of the hazardous condition onset of discovery.*
The weather conditions at the time of the hazardous conditions were: 84°F, WNW wind at 2.0 mph, 51% humidity, and no precipitation.

h. *The name, mailing address, and telephone number of the person reporting the hazardous condition.*
The person reporting the hazardous condition is Rob Saunders, Alliant Energy—Ottumwa Generating Station, 20775 Power Plant Road, Ottumwa, IA 52501, (641) 935-2971.


i. *The name and telephone of the person closest to the scene of the hazardous condition who can be contacted for further information and action.*
The person who can be contacted for further information is Rob Saunders, Alliant Energy—Ottumwa Generating Station, 20775 Power Plant Road, Ottumwa, IA 52501, (641) 935-2971.

j. *Any other information, such as the circumstances leading to the hazardous condition, visible effects, and containment measures taken that may assist in the proper evaluation by the department.*

The engine fuel line on a contractor's work truck started leaking diesel fuel. The contractor chose to drive this leaking fuel truck to their equipment laydown area in an attempt to fix the leak. They were unable to repair the leak, so they chose to remove the truck from our property. This left a trail of spilled diesel fuel all the way to the OGS front gate. No leaked fuel was observed on the county road. A lined dumpster was procured. Fuel contaminated soil from the contractor's equipment laydown area was scraped up and placed into the dumpster. Oil dry was applied to the spilled fuel on the concrete road and allowed to absorb for several hours. The oil dry was then cleaned up and placed in a dumpster for disposal at the local sanitary landfill.

Feel free to contact me if you have any additional questions.

Sincerely,



Rob Saunders

Sr. Environmental Specialist