



Heiderscheit, Mark <mark.heiderscheit@dnr.iowa.gov>

SIVYER_STEEL_Complaint.pdf

Smith, Heath <Smith.Heath@epa.gov>

Tue, May 2, 2017 at 5:06 PM

To: "Jamison, Kenneth" <Jamison.Kenneth@epa.gov>, R7 REOC <R7_REOC@epa.gov>, "mark.heiderscheit@dnr.iowa.gov" <mark.heiderscheit@dnr.iowa.gov>

Mark, thanks for taking my call. If you have any questions, please feel free to give me a call at 816-718-4277.

I believe this complaint was called in by an individual employed by Sivyer Steel. He believed actions Sivyer Steel are taking to dewater their foundary sand pit are wrong and wanted to report them. He says they are pumping water from a 30,000 gallon pit that contains contaminated foundary sand from their operations and the water is being released into the Mississippi River. The caller said they had been in trouble for doing this in the past.

2 attachments

[SIVYER_STEEL_Complaint.pdf](#)
57K

[ATT00001.txt](#)
1K



Call Log

[Return To List](#)

Call Date: 2017/05/02 (YYYY/MM/DD)	Call Time: 16:39 (HH:MM)	Duty Officer: HSMITH
Call Type: Incoming		
Receiver Information		
Name: HEATH SMITH		
Contact Information		
Name: ANONYMOUS		
Organization: SIVYER STEEL		
Contact Info: 225 33RD STREET BETTENDORF, SCOTT COUNTY, IOWA 52772 563-355-1811		
Incident Information		
Incident Type:	Spill	
Incident Description:	SIVYER STEEL IS PUMPING WATER FROM A 30,000 GALLON PIT INDIRECTLY INTO THE MISSISSIPPI RIVER. THE PIT CONTAINS FOUNDRY SAND.	
URL:	http://	
Notes		
CALLER WHO WISHES TO REMAIN ANONYMOUS, SAYS SIVYER STEEL IS PUMPING WATER OFF OF A 30,000 GALLON PIT OF FOUNDRY SAND VIA A TRASH PUMP. THEY ARE PUMPING THE WATER TO A STORM DRAIN. THE WATER IS THEN RELAYED TO THE MISSISSIPPI RIVER BY ANOTHER PUMP ON SITE. CALLER IS REPORTING THE INCIDENT BECAUSE HE BELIEVES THE ACTION IS WRONG. CALLER STATED THAT SIVYER STEEL HAS BEEN IN TROUBLE FOR DOING THIS BEFORE.		

DataID: 5217

[Return To List](#)