



NO EPA ID

NO DISCOVERY DATE

NPL Status = O-NOT A VALID SITE OR INCIDENTSite Name: Hawkeye Distribution Inc. Initiated Date 9/22/99 Initiated By: ☐ Removal ☒ Site AssessmentList Site Alias Name (s): Hawkeye Building SuppliesCON: 12-15
Doc # 16200Address: 204 Iowa Street County Name: WoodburyCity, State, Zip: South City, Ia. 51101 State ID (if one exists): _____ Congressional District: _____NPL Status: ☒ NOT A VALID SITE OR INCIDENTFederal Facility?: ☐ Yes ☒ NoSection: ☐ C-(SACR) Site Assessment/Cost Recovery Branch ☐ L-(EFLR) Enfr/Fund Lead RV Branch
☐ F-(FFSE) Federal Facilities/Apecial Emphasis Brnach ☐ M-(MOKS) MO/KS remedial Branch
☐ I-(IANE) IA/NE Remedial Branch ☐ O-(ER&R) Emergency Response & RV BranchDirections to Site: See MapSite Description: The site is a former railroad maintenance shop now used as a lumber yard. The lead contaminated area is around the R.R. paint shop.Site Size: 9Site Dimension: ☒ Acres ☐ Square Feet
☐ Feet ☐ Square Miles
☐ MilesSite Type: ☐ Disposal ☐ Storage
☐ Midnight Dump ☒ Transportation Related (former)
☐ Other ☐ Treatment
☐ Production Facility (active) ☐ Treatment (active)
☐ Production Facility (inactive)Owner Operator Type: ☐ Bank/Loan Company
☐ County Owned
☐ District Owned
☐ Federally Owned
☐ Former Federally Owned or Operated
☐ Government Owned/Contractor Operated
☐ Indian Lands
☐ Mixed Ownership
☐ Municipality
☐ Other
☒ Private
☐ Privately Owned/Government Operated
☐ Property Defaulted Back to Government
☐ State Owned
☐ Trustee, Federal
☐ Trustee, State
☐ UnknownIncident Type: ☒ Non-Oil Spill
☐ Oil Spill
☐ UnknownIncident Category: ☐ Abandoned ☐ Fire/Explosion
☐ Chemical Plant ☐ Landfill
☐ City Contamination ☐ Manufacturing Plant
☐ Dioxin ☐ Military Related
☐ Ecological Damage ☒ Other (painting overspray)
☐ Federal Facility ☐ Pure Lagoons
☐ Groundwater ☐ Radioactive Site
☐ Housing Area/Farm ☐ Mines/Tailings
☐ Industrial Waste Treatment
☐ Inorganic Waste ☐ Waterways/Creeks/Rivers
☐ Biological Threat ☐ Wells

RCRA Site: _____

USGS Quadrant: _____ USGS Hydro Unit: _____

Operational Status: ☒ Active As lumber yard
☒ Inactive As R.R. maintenance site
☐ UnknownLatitude: _____ Longitude: _____
Lat/Long Accuracy: ☐ Seconds ☐ Lat/Long Source:
☐ Meters ☐ EPA Region 7
☐ Feet ☐ EPIC
☐ Kilometers ☐ Geograph-Historical
☐ Miles ☐ Other
☐ 1 Degree ☐ Other Fed Agency
☐ PrivateAdd Action: ☒ PRE-CERCLIS SURVEYS Planned Complete: 1/1 Actual Complete: 1/10/00 OU 00Lead code (chosed one): ☒ F-EPA Fund Financed ☐ FF - Federal Facility ☐ S - State, Fund Financed SCAP Note: _____Comment: ☐ Site or ☒ Action: Site used a Environmental Agreement with a cap of asphalt & cement to protect the soil from leaching the lead.

Signatures: _____

State: Don Cook Date: 8/10/00 RPM/OSC/SAM: _____ Date 1/1