LETTER OF TRANSMITTAL

HRGreen 8710 Earhart Lane SW Cedar Rapids, IA 52404 319.841.4000 To: Mr. Mel Pins IDNR Brownfields Coordinator				⊠ Attac	April 16, 2012 10100200 Mr. Mel Pins Phase II Reports for Ottumwa Brownfields ending you the following items: hed or Separate Cover USPS or UPS	
502 E. 9th Street						
				e Order	☐ Samples ☐ Submittals ☐ Phase I and II ESA Reports	
Copies Da	te No.	No. Description				
1 each		Phase II Environmental Site Assessment Report for Hazardous Grant Sites: 327 E. Main Street and 331 E. Main Street, Ottumwa, Iowa				
1 each	Phase I Environmental Site Assessment Reports for Hazardous Grant Sites: 327 E. Main Street and 331 E. Main Street, Ottumwa, Iowa					
Hi Mel, Attached are copies of Phase I and II ESA reports completed for site adjacent properties in Ottumwa. Because the RECs were the same for both properties but ownership was different, separate reports were issued; however data points were shared. Mercury was detected in shallow soil (SB-4) on the 327 E. Main Street property. Petroleum contamination was detected in soil and groundwater (SB-3) at the 331 E. Main Street property. We are submitting these reports as the request of the City of Ottumwa for IDNR review and opinion of hazardous conditions. Thank you,						
Copies to: Nick Klimek, City of Ottumwa (transmittal only) Signed: Robin Husman						

05889 pm12:03 04/17/12