



July 19, 2019

DINO COSTANZO
DCJC LLC
273 S 62nd STREET
WEST DES MOINES IA 50266

NEAL THUENTES
VICTORIA CLEANERS INC
2164 NW 108th STREET
CLIVE IA 50325

Re: Remediation Site Monitoring Report, Victoria Cleaners, 2164 NW 108th Street, Clive, IA dated April 30, 2019 received June 12, 2019

Dear Mr. Costanzo and Mr. Thuentes:

The Iowa Department of Natural Resources, Contaminated Sites Section, has reviewed the above referenced report submitted by Seneca Companies on behalf of DCJC, LLC. and Victoria Cleaners, Inc. and accepts the report as written. For future reports the monitoring well statistical trend data should only include sample results collected after the November 2016 remediation event. The statistical trend analysis will start with the April 2017 data as noted in Iowa Administrative Code 567-137.10(2)e with the results reported in the next monitoring report. The statistical trend calculations will need to be included in the appendences.

Please let me know when the next sampling event is scheduled so I may have the opportunity to be on site. If you have any questions or need further information feel free to call or e-mail at (515) 725-8371 or dan.cook@dnr.iowa.gov.

Sincerely,

Daniel Cook
Environmental Specialist Senior
Contaminated Sites Section

c: Leslie Nagel, Seneca Companies, P.O. Box 3360, Des Moines, Iowa 50316-0360
Iowa DNR Field Office 5