

February 4, 2025

GABRIEL CAPAN  
HNI CORPORATION  
600 E 2<sup>ND</sup> ST  
MUSCATINE IA 52761

**Re: HON Oak Street Plant (301 Oak Street, Muscatine, IA)  
Contaminated Sites Database Site ID No. 67  
Review of Q1-Q4 2024 Free Product Monitoring Reports**

Dear Mr. Capan,

The Iowa Department of Natural Resources (DNR) has received Free Product Summary Reports from the 1<sup>st</sup> through 4<sup>th</sup> quarters of 2024; thank you for your submissions. Based on the summary reports, active free product recovery was completed monthly at monitoring well MW-11 with monthly monitoring completed at MW-13 per DNR correspondence dated May 16, 2022. Free product measurement and recovery totals at both MW-11 and MW-13 continue to fluctuate, but remain in line with recent results and show an overall decreasing trend since free product recovery was initiated at the site.

Please be aware, the 0.2 feet monitoring termination criteria referenced in the May 16, 2022 letter is incorrect and should read 0.02 feet as outlined on page 4 of the 2010 Free Product Assessment and Recovery Work Plan. However, the DNR acknowledges the significant decline in free product recovery totals and that a point of diminishing returns may have been reached with consideration to ongoing recovery. The recommended shift to a 6-month period of monitoring for MW-11 is accepted at this time. Please continue monitoring efforts in accordance with the 2010 Work Plan and subsequent revisions.

Feel free to contact me with any questions at [\(515\) 721-7024](tel:5157217024) or by email at [andrew.carver@dnr.iowa.gov](mailto:andrew.carver@dnr.iowa.gov).

Sincerely,

Andrew Carver, CGP  
Environmental Specialist  
Land Quality Bureau

cc: Iowa DNR Field Office #6  
Washington, IA

Michael Sullivan  
Iowa DNR  
6200 Park Ave Ste 200  
Des Moines, IA 50321

Jesse Nelson  
Terracon Consultants, Inc.