

PetroNetwork S3

CITLDS Continual Reconciliation Report - 08/15/2019

This report provides the results of continual reconciliation testing for tanks and associated lines for monthly monitoring.

Tank Owner	QuikTrip Corporation
	4705 South 129th East Ave.
	Tulsa, OK 74134
Facility Name	Quiktrip-Des Moines-0554 - 0554 - W90573
Facility Location	901 Sw 63rd St
	Des Moines, IA 50312-1621

Tank Monitoring Report

Tank ID – Product	Tank Capacity	Test Dates	System Status Pass Fail Inconclusive	Monthly Monitoring Period
01-R	12000	07/17/2019-08/15/2019	Pass	07/17/2019-08/15/2019
03-S	12000	07/17/2019-08/15/2019	Pass	07/17/2019-08/15/2019
07-R	12000	07/17/2019-08/15/2019	Pass	07/17/2019-08/15/2019
09-A	12000	07/17/2019-08/15/2019	Pass	07/17/2019-08/15/2019

Line Monitoring Report

Associated Tank ID – Product	Tank System Capacity	Test Dates	System Status Pass Fail Inconclusive	Monthly Monitoring Period
01-R	12000	07/17/2019-08/15/2019	Pass	07/17/2019-08/15/2019
03-S	12000	07/17/2019-08/15/2019	Pass	07/17/2019-08/15/2019
07-R	12000	07/17/2019-08/15/2019	Pass	07/17/2019-08/15/2019
09-A	12000	07/17/2019-08/15/2019	Pass	07/17/2019-08/15/2019

Monthly Monitoring Data Quality Report

Associated Tank ID – Product	Tank System Capacity	Test Dates	Minimum Detectable Leak (gph)	Threshold (gph)
01-R	12000	07/17/2019-08/15/2019	0.030	0.015
03-S	12000	07/17/2019-08/15/2019	0.030	0.015
07-R	12000	07/17/2019-08/15/2019	0.030	0.015
09-A	12000	07/17/2019-08/15/2019	0.030	0.015

PetroNetwork S3

CITLDS Continual Reconciliation Report - 07/16/2019

This report provides the results of continual reconciliation testing for tanks and associated lines for monthly monitoring.

Tank Owner	QuikTrip Corporation
	4705 South 129th East Ave.
	Tulsa, OK 74134
Facility Name	Quiktrip-Des Moines-0554 - 0554 - W90573
Facility Location	901 Sw 63rd St
	Des Moines, IA 50312-1621

Tank Monitoring Report

Tank ID – Product	Tank Capacity	Test Dates	System Status Pass Fail Inconclusive	Monthly Monitoring Period
01-R	12000	06/17/2019-07/16/2019	Pass	06/17/2019-07/16/2019
03-S	12000	06/17/2019-07/16/2019	Pass	06/17/2019-07/16/2019
07-R	12000	06/22/2019-07/10/2019	Pass	06/17/2019-07/16/2019
09-A	12000	06/17/2019-07/16/2019	Pass	06/17/2019-07/16/2019

Line Monitoring Report

Associated Tank ID – Product	Tank System Capacity	Test Dates	System Status Pass Fail Inconclusive	Monthly Monitoring Period
01-R	12000	06/17/2019-07/16/2019	Pass	06/17/2019-07/16/2019
03-S	12000	06/17/2019-07/16/2019	Pass	06/17/2019-07/16/2019
07-R	12000	06/22/2019-07/10/2019	Pass	06/17/2019-07/16/2019
09-A	12000	06/17/2019-07/16/2019	Pass	06/17/2019-07/16/2019

Monthly Monitoring Data Quality Report

Associated Tank ID – Product	Tank System Capacity	Test Dates	Minimum Detectable Leak (gph)	Threshold (gph)
01-R	12000	06/17/2019-07/16/2019	0.040	0.020
03-S	12000	06/17/2019-07/16/2019	0.030	0.015
07-R	12000	06/22/2019-07/10/2019	0.140	0.070
09-A	12000	06/17/2019-07/16/2019	0.030	0.015

PetroNetwork S3

CITLDS Continual Reconciliation Report - 06/16/2019

This report provides the results of continual reconciliation testing for tanks and associated lines for monthly monitoring.

Tank Owner	QuikTrip Corporation
	4705 South 129th East Ave.
	Tulsa, OK 74134
Facility Name	Quiktrip-Des Moines-0554 - 0554 - W90573
Facility Location	901 Sw 63rd St
	Des Moines, IA 50312-1621

Tank Monitoring Report

Tank ID – Product	Tank Capacity	Test Dates	System Status Pass Fail Inconclusive	Monthly Monitoring Period
01-R	12000	05/18/2019-06/16/2019	Pass	05/18/2019-06/16/2019
03-S	12000	05/18/2019-06/16/2019	Pass	05/18/2019-06/16/2019
07-R	12000	05/18/2019-06/10/2019	Pass	05/18/2019-06/16/2019
09-A	12000	05/18/2019-06/16/2019	Pass	05/18/2019-06/16/2019

Line Monitoring Report

Associated Tank ID – Product	Tank System Capacity	Test Dates	System Status Pass Fail Inconclusive	Monthly Monitoring Period
01-R	12000	05/18/2019-06/16/2019	Pass	05/18/2019-06/16/2019
03-S	12000	05/18/2019-06/16/2019	Pass	05/18/2019-06/16/2019
07-R	12000	05/18/2019-06/10/2019	Pass	05/18/2019-06/16/2019
09-A	12000	05/18/2019-06/16/2019	Pass	05/18/2019-06/16/2019

Monthly Monitoring Data Quality Report

Associated Tank ID – Product	Tank System Capacity	Test Dates	Minimum Detectable Leak (gph)	Threshold (gph)
01-R	12000	05/18/2019-06/16/2019	0.030	0.015
03-S	12000	05/18/2019-06/16/2019	0.030	0.015
07-R	12000	05/18/2019-06/10/2019	0.030	0.015
09-A	12000	05/18/2019-06/16/2019	0.030	0.015

PetroNetwork S3

CITLDS Continual Reconciliation Report - 05/17/2019

This report provides the results of continual reconciliation testing for tanks and associated lines for monthly monitoring.

Tank Owner	QuikTrip Corporation
	4705 South 129th East Ave.
	Tulsa, OK 74134
Facility Name	Quiktrip-Des Moines-0554 - 0554 - W90573
Facility Location	901 Sw 63rd St
	Des Moines, IA 50312-1621

Tank Monitoring Report

Tank ID – Product	Tank Capacity	Test Dates	System Status Pass Fail Inconclusive	Monthly Monitoring Period
01-R	12000	04/18/2019-05/17/2019	Pass	04/18/2019-05/17/2019
03-S	12000	04/18/2019-05/17/2019	Pass	04/18/2019-05/17/2019
07-R	12000	04/18/2019-05/17/2019	Pass	04/18/2019-05/17/2019
09-A	12000	04/18/2019-05/17/2019	Pass	04/18/2019-05/17/2019

Line Monitoring Report

Associated Tank ID – Product	Tank System Capacity	Test Dates	System Status Pass Fail Inconclusive	Monthly Monitoring Period
01-R	12000	04/18/2019-05/17/2019	Pass	04/18/2019-05/17/2019
03-S	12000	04/18/2019-05/17/2019	Pass	04/18/2019-05/17/2019
07-R	12000	04/18/2019-05/17/2019	Pass	04/18/2019-05/17/2019
09-A	12000	04/18/2019-05/17/2019	Pass	04/18/2019-05/17/2019

Monthly Monitoring Data Quality Report

Associated Tank ID – Product	Tank System Capacity	Test Dates	Minimum Detectable Leak (gph)	Threshold (gph)
01-R	12000	04/18/2019-05/17/2019	0.030	0.015
03-S	12000	04/18/2019-05/17/2019	0.030	0.015
07-R	12000	04/18/2019-05/17/2019	0.030	0.015
09-A	12000	04/18/2019-05/17/2019	0.030	0.015

PetroNetwork S3

CITLDS Continual Reconciliation Report - 04/17/2019

This report provides the results of continual reconciliation testing for tanks and associated lines for monthly monitoring.

Tank Owner	QuikTrip Corporation
	4705 South 129th East Ave.
	Tulsa, OK 74134
Facility Name	Quiktrip-Des Moines-0554 - 0554 - W90573
Facility Location	901 Sw 63rd St
	Des Moines, IA 50312-1621

Tank Monitoring Report

Tank ID – Product	Tank Capacity	Test Dates	System Status Pass Fail Inconclusive	Monthly Monitoring Period
01-R	12000	03/19/2019-04/17/2019	Pass	03/19/2019-04/17/2019
03-S	12000	03/19/2019-04/17/2019	Pass	03/19/2019-04/17/2019
07-R	12000	03/19/2019-04/17/2019	Pass	03/19/2019-04/17/2019
09-A	12000	03/20/2019-04/17/2019	Pass	03/19/2019-04/17/2019

Line Monitoring Report

Associated Tank ID – Product	Tank System Capacity	Test Dates	System Status Pass Fail Inconclusive	Monthly Monitoring Period
01-R	12000	03/19/2019-04/17/2019	Pass	03/19/2019-04/17/2019
03-S	12000	03/19/2019-04/17/2019	Pass	03/19/2019-04/17/2019
07-R	12000	03/19/2019-04/17/2019	Pass	03/19/2019-04/17/2019
09-A	12000	03/20/2019-04/17/2019	Pass	03/19/2019-04/17/2019

Monthly Monitoring Data Quality Report

Associated Tank ID – Product	Tank System Capacity	Test Dates	Minimum Detectable Leak (gph)	Threshold (gph)
01-R	12000	03/19/2019-04/17/2019	0.030	0.015
03-S	12000	03/19/2019-04/17/2019	0.030	0.015
07-R	12000	03/19/2019-04/17/2019	0.030	0.015
09-A	12000	03/20/2019-04/17/2019	0.030	0.015

PetroNetwork S3

CITLDS Continual Reconciliation Report - 3/18/2019

This report provides the results of continual reconciliation testing for tanks and associated lines for monthly monitoring.

Tank Owner	QuikTrip Corporation
	4705 South 129th East Ave.
	Tulsa, OK 74134
Facility Name	Quiktrip-Des Moines-0554 - 0554 - W90573
Facility Location	901 Sw 63rd St
	Des Moines, IA 50312-1621

Tank Monitoring Report

Tank ID – Product	Tank Capacity	Test Dates	System Status Pass Fail Inconclusive	Monthly Monitoring Period
01-R	12000	02/17/2019-03/18/2019	Pass	2/17/2019-3/18/2019
03-S	12000	02/17/2019-03/18/2019	Pass	2/17/2019-3/18/2019
07-R	12000	02/17/2019-03/18/2019	Pass	2/17/2019-3/18/2019
09-A	12000	02/17/2019-03/18/2019	Pass	2/17/2019-3/18/2019

Line Monitoring Report

Associated Tank ID – Product	Tank System Capacity	Test Dates	System Status Pass Fail Inconclusive	Monthly Monitoring Period
01-R	12000	02/17/2019-03/18/2019	Pass	2/17/2019-3/18/2019
03-S	12000	02/17/2019-03/18/2019	Pass	2/17/2019-3/18/2019
07-R	12000	02/17/2019-03/18/2019	Pass	2/17/2019-3/18/2019
09-A	12000	02/17/2019-03/18/2019	Pass	2/17/2019-3/18/2019

Monthly Monitoring Data Quality Report

Associated Tank ID – Product	Tank System Capacity	Test Dates	Minimum Detectable Leak (gph)	Threshold (gph)
01-R	12000	02/17/2019-03/18/2019	0.030	0.015
03-S	12000	02/17/2019-03/18/2019	0.030	0.015
07-R	12000	02/17/2019-03/18/2019	0.030	0.015
09-A	12000	02/17/2019-03/18/2019	0.040	0.020

PetroNetwork S3

CITLDS Continual Reconciliation Report - 2/16/2019

This report provides the results of continual reconciliation testing for tanks and associated lines for monthly monitoring.

Tank Owner	QuikTrip Corporation
	4705 South 129th East Ave.
	Tulsa, OK 74134
Facility Name	Quiktrip-Des Moines-0554 - 0554 - W90573
Facility Location	901 Sw 63Rd St
	Des Moines, IA 50312-1621

Tank Monitoring Report

Tank ID – Product	Tank Capacity	Test Dates	System Status Pass Fail Inconclusive	Monthly Monitoring Period
01-R	12000	01/18/2019-02/16/2019	Pass	1/18/2019-2/16/2019
03-S	12000	01/18/2019-02/16/2019	Pass	1/18/2019-2/16/2019
07-R	12000	01/18/2019-02/16/2019	Pass	1/18/2019-2/16/2019
09-A	12000	01/18/2019-02/16/2019	Pass	1/18/2019-2/16/2019

Line Monitoring Report

Associated Tank ID – Product	Tank System Capacity	Test Dates	System Status Pass Fail Inconclusive	Monthly Monitoring Period
01-R	12000	01/18/2019-02/16/2019	Pass	1/18/2019-2/16/2019
03-S	12000	01/18/2019-02/16/2019	Pass	1/18/2019-2/16/2019
07-R	12000	01/18/2019-02/16/2019	Pass	1/18/2019-2/16/2019
09-A	12000	01/18/2019-02/16/2019	Pass	1/18/2019-2/16/2019

Monthly Monitoring Data Quality Report

Associated Tank ID – Product	Tank System Capacity	Test Dates	Minimum Detectable Leak (gph)	Threshold (gph)
01-R	12000	01/18/2019-02/16/2019	0.040	0.020
03-S	12000	01/18/2019-02/16/2019	0.030	0.015
07-R	12000	01/18/2019-02/16/2019	0.030	0.015
09-A	12000	01/18/2019-02/16/2019	0.030	0.015

PetroNetwork S3

CITLDS Continual Reconciliation Report - 1/17/2019

This report provides the results of continual reconciliation testing for tanks and associated lines for monthly monitoring.

Tank Owner	QuikTrip Corporation
	4705 South 129th East Ave.
	Tulsa, OK 74134
Facility Name	Quiktrip-Des Moines-0554 - 0554 - W90573
Facility Location	901 Sw 63Rd St
	Des Moines, IA 50312-1621

Tank Monitoring Report

Tank ID – Product	Tank Capacity	Test Dates	System Status Pass Fail Inconclusive	Monthly Monitoring Period
01-R	12000	01/05/2019-01/17/2019	Pass	12/19/2018-1/17/2019
03-S	12000	12/19/2018-01/17/2019	Pass	12/19/2018-1/17/2019
07-R	12000	01/05/2019-01/17/2019	Pass	12/19/2018-1/17/2019
09-A	12000	12/19/2018-01/17/2019	Pass	12/19/2018-1/17/2019

Line Monitoring Report

Associated Tank ID – Product	Tank System Capacity	Test Dates	System Status Pass Fail Inconclusive	Monthly Monitoring Period
01-R	12000	01/05/2019-01/17/2019	Pass	12/19/2018-1/17/2019
03-S	12000	12/19/2018-01/17/2019	Pass	12/19/2018-1/17/2019
07-R	12000	01/05/2019-01/17/2019	Pass	12/19/2018-1/17/2019
09-A	12000	12/19/2018-01/17/2019	Pass	12/19/2018-1/17/2019

Monthly Monitoring Data Quality Report

Associated Tank ID – Product	Tank System Capacity	Test Dates	Minimum Detectable Leak (gph)	Threshold (gph)
01-R	12000	01/05/2019-01/17/2019	0.030	0.015
03-S	12000	12/19/2018-01/17/2019	0.030	0.015
07-R	12000	01/05/2019-01/17/2019	0.030	0.015
09-A	12000	12/19/2018-01/17/2019	0.030	0.015

PetroNetwork S3

CITLDS Continual Reconciliation Report - 12/18/2018

This report provides the results of continual reconciliation testing for tanks and associated lines for monthly monitoring.

Tank Owner	QuikTrip Corporation
	4705 South 129th East Ave.
	Tulsa, OK 74134
Facility Name	Quiktrip-Des Moines-0554 - 0554 - W90573
Facility Location	901 Sw 63Rd St
	Des Moines, IA 50312-1621

Tank Monitoring Report

Tank ID – Product	Tank Capacity	Test Dates	System Status Pass Fail Inconclusive	Monthly Monitoring Period
01-R	12000	11/19/2018-12/18/2018	Pass	11/19/2018-12/18/2018
03-S	12000	11/19/2018-12/18/2018	Pass	11/19/2018-12/18/2018
07-R	12000	11/19/2018-12/18/2018	Pass	11/19/2018-12/18/2018
09-A	12000	11/19/2018-12/18/2018	Pass	11/19/2018-12/18/2018

Line Monitoring Report

Associated Tank ID – Product	Tank System Capacity	Test Dates	System Status Pass Fail Inconclusive	Monthly Monitoring Period
01-R	12000	11/19/2018-12/18/2018	Pass	11/19/2018-12/18/2018
03-S	12000	11/19/2018-12/18/2018	Pass	11/19/2018-12/18/2018
07-R	12000	11/19/2018-12/18/2018	Pass	11/19/2018-12/18/2018
09-A	12000	11/19/2018-12/18/2018	Pass	11/19/2018-12/18/2018

Monthly Monitoring Data Quality Report

Associated Tank ID – Product	Tank System Capacity	Test Dates	Minimum Detectable Leak (gph)	Threshold (gph)
01-R	12000	11/19/2018-12/18/2018	0.030	0.015
03-S	12000	11/19/2018-12/18/2018	0.030	0.015
07-R	12000	11/19/2018-12/18/2018	0.030	0.015
09-A	12000	11/19/2018-12/18/2018	0.030	0.015

PetroNetwork S3

CITLDS Continual Reconciliation Report - 11/18/2018

This report provides the results of continual reconciliation testing for tanks and associated lines for monthly monitoring.

Tank Owner	QuikTrip Corporation
	4705 South 129th East Ave.
	Tulsa, OK 74134
Facility Name	Quiktrip-Des Moines-0554 - 0554 - W90573
Facility Location	901 Sw 63Rd St
	Des Moines, IA 50312-1621

Tank Monitoring Report

Tank ID – Product	Tank Capacity	Test Dates	System Status Pass Fail Inconclusive	Monthly Monitoring Period
01-R	12000	10/20/2018-11/18/2018	Pass	10/20/2018-11/18/2018
03-S	12000	10/20/2018-11/18/2018	Pass	10/20/2018-11/18/2018
07-R	12000	10/20/2018-11/18/2018	Pass	10/20/2018-11/18/2018
09-A	12000	10/20/2018-11/18/2018	Pass	10/20/2018-11/18/2018

Line Monitoring Report

Associated Tank ID – Product	Tank System Capacity	Test Dates	System Status Pass Fail Inconclusive	Monthly Monitoring Period
01-R	12000	10/20/2018-11/18/2018	Pass	10/20/2018-11/18/2018
03-S	12000	10/20/2018-11/18/2018	Pass	10/20/2018-11/18/2018
07-R	12000	10/20/2018-11/18/2018	Pass	10/20/2018-11/18/2018
09-A	12000	10/20/2018-11/18/2018	Pass	10/20/2018-11/18/2018

Monthly Monitoring Data Quality Report

Associated Tank ID – Product	Tank System Capacity	Test Dates	Minimum Detectable Leak (gph)	Threshold (gph)
01-R	12000	10/20/2018-11/18/2018	0.030	0.015
03-S	12000	10/20/2018-11/18/2018	0.030	0.015
07-R	12000	10/20/2018-11/18/2018	0.030	0.015
09-A	12000	10/20/2018-11/18/2018	0.030	0.015

PetroNetwork S3

CITLDS Continual Reconciliation Report - 10/19/2018

This report provides the results of continual reconciliation testing for tanks and associated lines for monthly monitoring.

Tank Owner	QuikTrip Corporation
	4705 South 129th East Ave.
	Tulsa, OK 74134
Facility Name	Quiktrip-Des Moines-0554 - 0554 - W90573
Facility Location	901 Sw 63Rd St
	Des Moines, IA 50312-1621

Tank Monitoring Report

Tank ID – Product	Tank Capacity	Test Dates	System Status Pass Fail Inconclusive	Monthly Monitoring Period
01-R	12000	09/20/2018-10/08/2018	Pass	9/20/2018-10/19/2018
03-S	12000	09/20/2018-10/08/2018	Pass	9/20/2018-10/19/2018
07-R	12000	09/20/2018-10/08/2018	Pass	9/20/2018-10/19/2018
09-A	12000	09/20/2018-10/08/2018	Pass	9/20/2018-10/19/2018

Line Monitoring Report

Associated Tank ID – Product	Tank System Capacity	Test Dates	System Status Pass Fail Inconclusive	Monthly Monitoring Period
01-R	12000	09/20/2018-10/08/2018	Pass	9/20/2018-10/19/2018
03-S	12000	09/20/2018-10/08/2018	Pass	9/20/2018-10/19/2018
07-R	12000	09/20/2018-10/08/2018	Pass	9/20/2018-10/19/2018
09-A	12000	09/20/2018-10/08/2018	Pass	9/20/2018-10/19/2018

Monthly Monitoring Data Quality Report

Associated Tank ID – Product	Tank System Capacity	Test Dates	Minimum Detectable Leak (gph)	Threshold (gph)
01-R	12000	09/20/2018-10/08/2018	0.030	0.015
03-S	12000	09/20/2018-10/08/2018	0.030	0.015
07-R	12000	09/20/2018-10/08/2018	0.030	0.015
09-A	12000	09/20/2018-10/08/2018	0.030	0.015

PetroNetwork S3

CITLDS Continual Reconciliation Report - 9/19/2018

This report provides the results of continual reconciliation testing for tanks and associated lines for monthly monitoring.

Tank Owner	QuikTrip Corporation
	4705 South 129th East Ave.
	Tulsa, OK 74134
Facility Name	Quiktrip-Des Moines-0554 - 0554 - W90573
Facility Location	901 Sw 63Rd St
	Des Moines, IA 50312-1621

Tank Monitoring Report

Tank ID – Product	Tank Capacity	Test Dates	System Status Pass Fail Inconclusive	Monthly Monitoring Period
01-R	12000	08/21/2018-09/19/2018	Pass	8/21/2018-9/19/2018
03-S	12000	08/21/2018-09/19/2018	Pass	8/21/2018-9/19/2018
07-R	12000	08/21/2018-09/19/2018	Pass	8/21/2018-9/19/2018
09-A	12000	08/21/2018-09/19/2018	Pass	8/21/2018-9/19/2018

Line Monitoring Report

Associated Tank ID – Product	Tank System Capacity	Test Dates	System Status Pass Fail Inconclusive	Monthly Monitoring Period
01-R	12000	08/21/2018-09/19/2018	Pass	8/21/2018-9/19/2018
03-S	12000	08/21/2018-09/19/2018	Pass	8/21/2018-9/19/2018
07-R	12000	08/21/2018-09/19/2018	Pass	8/21/2018-9/19/2018
09-A	12000	08/21/2018-09/19/2018	Pass	8/21/2018-9/19/2018

Monthly Monitoring Data Quality Report

Associated Tank ID – Product	Tank System Capacity	Test Dates	Minimum Detectable Leak (gph)	Threshold (gph)
01-R	12000	08/21/2018-09/19/2018	0.030	0.015
03-S	12000	08/21/2018-09/19/2018	0.030	0.015
07-R	12000	08/21/2018-09/19/2018	0.030	0.015
09-A	12000	08/21/2018-09/19/2018	0.030	0.015

PetroNetwork S3

CITLDS Continual Reconciliation Report - 8/20/2018

This report provides the results of continual reconciliation testing for tanks and associated lines for monthly monitoring.

Tank Owner	QuikTrip Corporation
	4705 South 129th East Ave.
	Tulsa, OK 74134
Facility Name	Quiktrip-Des Moines-0554 - 0554 - W90573
Facility Location	901 Sw 63Rd St
	Des Moines, IA 50312-1621

Tank Monitoring Report

Tank ID – Product	Tank Capacity	Test Dates	System Status Pass Fail Inconclusive	Monthly Monitoring Period
01-R	12000	07/22/2018-08/20/2018	Pass	7/22/2018-8/20/2018
03-S	12000	07/22/2018-08/20/2018	Pass	7/22/2018-8/20/2018
07-R	12000	07/22/2018-08/20/2018	Pass	7/22/2018-8/20/2018
09-A	12000	07/22/2018-08/20/2018	Pass	7/22/2018-8/20/2018

Line Monitoring Report

Associated Tank ID – Product	Tank System Capacity	Test Dates	System Status Pass Fail Inconclusive	Monthly Monitoring Period
01-R	12000	07/22/2018-08/20/2018	Pass	7/22/2018-8/20/2018
03-S	12000	07/22/2018-08/20/2018	Pass	7/22/2018-8/20/2018
07-R	12000	07/22/2018-08/20/2018	Pass	7/22/2018-8/20/2018
09-A	12000	07/22/2018-08/20/2018	Pass	7/22/2018-8/20/2018

Monthly Monitoring Data Quality Report

Associated Tank ID – Product	Tank System Capacity	Test Dates	Minimum Detectable Leak (gph)	Threshold (gph)
01-R	12000	07/22/2018-08/20/2018	0.030	0.015
03-S	12000	07/22/2018-08/20/2018	0.030	0.015
07-R	12000	07/22/2018-08/20/2018	0.030	0.015
09-A	12000	07/22/2018-08/20/2018	0.030	0.015