

DIRECTOR KAYLA LYON

November 16, 2022

ALL METALS RECYCLING ATTN: MATT WILSON 404 N FORREST AVENUE OTTUMWA, IA 52501

SUBJECT: All Metals Recycling ADP Compliance Inspection; FOCD Inspection #87757 ADP Permit No. 90-ADP-04-12, All Metals Recycling, Ottumwa, IA

Dear Mr. Wilson:

I conducted an inspection of the All Metals Recycling ADP located at 404 N Forrest Avenue in Ottumwa. The enclosed report outlines various items observed during the course of my inspection. Ensure to review the comments section of the report.

If you have any questions or would like further explanation of any part of this report, please contact me at this office at 319-653-2135.

Sincerely,

FIELD SERVICES & COMPLIANCE BUREAU

Bert Noll

Environmental Specialist

Encl. ADP Inspection Report

N:FO6\bnoll\sw\All Metals ADP cover 10-22 N:FO6\bnoll\sw\All Metals ADP insp 10-22

xc: Becky Jolly, IDNR Solid Waste Section, via email SW\All Metals ADP File

IOWA DEPARTMENT OF NATURAL RESOURCES APPLIANCE DEMANUFACTURING (ADP) PERMIT INSPECTION FORM

Permit No.:90-ADP-04-12	County:Wapello
Facility Name:All Metals Recycling	Facility Address:
	404 N Forrest Avenue, Ottumwa 52501
Phone Number:641-684-5300	
Responsible Official:Matt Wilson	Mailing Address:
	Same
Phone Number:641-799-8999	
Person(s) Present:	
1)Matt Wilson - Alters	
2)Jeremiah Kaufmann - DNR	
3)	
Date of This Inspection:10/27/22	Date of Last Inspection:12/4/17
*Re advised your facility may require due to either SIC code or ousite manage	gement practices an NPDES General Permit #1 (Stormwater permit)

	IAC 567 C	hapter 118.4: Appliance Storage & Handling Prior to Demanufacturing	Yes	No	NA
Handling	118.4(1)	Are appliances being stored to prevent capacitors, refrigerant lines, compressors, and components containing mercury from being damaged and allowing a release into the environment?	\boxtimes		
Storage & H	118.4(2)	Are appliances being handled in a way which prevents damage, cuts, or breaks in refrigerant lines, compressors, capacitors and components containing mercury from being damaged and allowing a release into the environment?	\boxtimes		
S	118.4(3)	Are less than 1,000 appliances being stored prior to demanufacturing?	\boxtimes		
	118.4(4)	Are appliances being demanufactured in 270 days or less?	\boxtimes		

Operations	IAC 567 C	hapter 118.7: Fixed Facility & Mobile Operations	Yes	No	NA
fions	118.7(1)	Is demanufacturing taking place on an impervious floor (including but not limited to concrete, ceramic tile, or metal)?	\boxtimes		
Opera	118.7(2)	Is the point of demanufacturing located 50 feet or more from a well and any water of the state?	\boxtimes		
Operations	118.7(5)	Is a unique marking system (minimum of nine inches square) being applied to the appliances after demanufacturing?	×.		

 51	IAC 567 C	hapter 118.8: Training	Yes	No	NA
ainin	118.8	Is at least one owner or employee completed a Department-approved training course?	\boxtimes		
ining	118.8	Is one trained person on site at all times when appliances are being demanufactured?			

	IAC 567 CI	hapter 118.6: Permit Application Requirements	Yes	No	NA
	118.6(8)	Is a copy of the EPA Refrigerant Recovery or Recycling Devise Acquisition Certification available onsite?			\boxtimes
	608 CAA (CFR)	Is a copy of the EPA Refrigerant Reclaimer's Certification available onsite if reclamation (purification) is taking place at the facility?			\boxtimes
over	IAC 567 CI	napter 118.9: Refrigerant Removal Requirements	Yes	No	NA
ant Rec	118.9(2)	If refrigerant is removed at a location other than a permitted ADP facility, is there documentation that it was removed by a service or repair facility certified for the removal of refrigerant?			
Refriger	118.9(3)	Is removal of refrigerant being done in an area where the temperature of the surrounding air and that of the appliance being demanufactured is 45 degrees Fahrenheit or greater?	\boxtimes		
		napter 118.13: Record Keeping & Reporting	Yes	No	NA
	118.13(2)"a" & 118.13(2)"g"	Are the number and type of refrigerant containing appliances being tracked, as well as the amount of refrigerant removed?	\boxtimes		
Ammonia Gas Refrigerant Oil Refrigerant Recovery 1	118.13(3)"a"	Are bills of lading being kept as to where refrigerants are being shipped for disposal?			
					1
	IAC 567 CH	napter 118.9: Refrigerant Removal Requirements	Yes	No	NA
O	118.9(5)	If compressor oil is being removed from the refrigeration units, is it being stored in accordance with 567-119.5 (Note: AST must be large enough and on an impermeable surface to prevent spills, meet API construction standards, have absorbent material available, have a gauge to monitor liquid level, & meet Ch. 567-135 &136 if UST)			\boxtimes
					
	IAC 567 C	hapter 118.9: Refrigerant Removal Requirements	Yes	No	NA
	118.9(6)"a"	Is the ammonia gas being vented into water and is the resulting wastewater being properly disposed of?			\boxtimes
gerant	118.9(6)"e"	Is sodium chromate being properly stored in DOT-approved containers labeled with a proper EPA-approved chromium label stating "chromium" or "hazardous waste"?			\boxtimes
Refri	118.9(6)"g"	Does the facility have an EPA ID number (RCRA)?			\boxtimes
Ammonia Gas Refrigerant Recovery 1	118.9(6)"h" & 118.9(6)"i"	Is asbestos insulation being removed and handled properly?			\boxtimes
ionia	IAC 567 C	hapter 118.13: Record Keeping & Reporting	Yes	No	NA
Water Property of the property	118.13(2)"a"(2	Are records being kept on the number of sodium chromate–containing appliances being demanufactured			\boxtimes
•	118.13(2)" <i>f</i> "	Are records being kept on the number of addition abromate containing			\boxtimes
	118.13(3)"a" (118.13(3)"b"	Are records being kept on the shipment of sodium chromate (name of the			\boxtimes

	IAC 567 C	hapter 118.10: Mercury-Containing Component Removal & Disposal	Yes	No	NA
	118.10(1)	Are all components containing mercury being removed?	\boxtimes		
S	118.10(2)	Are mercury components being stored in containers with a proper EPA- approved label stating "Universal Waste-Mercury Containing Equipment", or Waste Mercury-Containing Equipment" in both English and the predominant language of any non-English-reading workers?			
nenc	118.10(3)	Is the date when the first mercury-containing component was placed in the container affixed to the container?	\boxtimes		
Components	118.10(4)	Storage of mercury is limited to one year, after which, it must be transported to an EPA-approved recycler/recovery facility. Has storage been under one year?	\boxtimes		
Mercury	118.10(8)	Are fluorescent tubes, lamps, bulbs, etc., being placed in a container and packaged to prevent breakage to an EPA-approved recycler?	\boxtimes		
₩	IAC 567 C	hapter 118.13: Record Keeping & Reporting	Yes	No	NA
	118.13(2)	Are records being kept on the number of mercury-containing appliances being demanufactured, number of mercury switches removed, number of fluorescent tubes removed, as well as the number of mercury thermocouples being removed?	\boxtimes		
	118.13(3)	Are records or bills of ladings being kept on the shipment of mercury-containing components?	\boxtimes		

	IAC 567 Ch	apter 118.11: Capacitor Removal Requirements	Yes	No	NA
	118.11(4)" <i>a</i> "	Does the facility have an EPA TSCA ID number for capacitor storage (required if facility has no RCRA ID #)?	\boxtimes		
	118.11(4)" <i>b</i> "	Are PCB items being stored in a manner that provides adequate protection from the elements and adequate secondary containment? (Note: Storage must take place on an impervious material above the 100-year floodwater elevation)	\boxtimes		
Ø	118.11(4)"c"	Is the point of demanufacturing located above the 100-year flood water elevation?	\boxtimes		
Capacitors	118.11(4)" <i>d</i> "	Are PCB storage containers filled to two inches of absorbent material in the bottom?		\boxtimes	
Capa	118.11(4)"e"	Are PCB containers DOT-approved and labeled with a 6" by 6" yellow label stating "PCBs" as described in CFR part 761.45?			
PCB	118.11(4)"g"	Is the storage for non leaking small PCB capacitors that do not comply with the requirements in 118.11(4) "a" to "f" stored for less than 30 days from the date of removal and a notation places on the PCB capacitor indicating the date the item was removed from the appliance?	\boxtimes		
PCB C	118.11(4)"f" & 118.11(4)"h"	Is the date when the first capacitor was placed in the storage container on the label? Storage of capacitors is limited to 270 days, after which they must be transported to an EPA-approved landfill or incinerator. This burial or incineration must be documented (within one year of the date on the container) and this record kept by the demanufacturer for three years from the date the PCB waste was accepted by the initial transporter.			

PCB Capacitors	IAC 567 CI	าapter 118.13: Record Keeping & Reporting	Yes	No	NA
	118.13(2)	Are records being kept on the number of PCB containing appliances being demanufactured, number of PCB capacitors and ballasts as well as the date the first PCB-containing item was placed in the storage drum that is in use on December 31? number of mercury thermocouples being removed?			
	118.13(3)"a" & 118.13(3)" <i>b</i> "	Are records being kept on the shipment of PCB components and the documentation of destruction or receipt from a regional collection center for all-PCB materials shipped?			
	118.13(3)" <i>d</i> "	Are records being kept documenting inspections of the PCB storage area as required by 118.11(4)"h"?			

Comments: PCB items were being stored in an appropriate bucket but it did not have absorbent material in it. Mr. Wilson indicated he would add some.

Spills	IAC 567 C	hapter 118.12: Spills	Yes	No	NA
	118.12(1)	Are spill records being kept and has the facility reported spills that resulted in a hazardous condition?			\boxtimes
	118.12(2)	Is a mercury spill kit on hand?	\boxtimes		

Reporting	IAC 567 C	hapter 118.13. Record Keeping & Reporting	Yes	No	NA
ting	118.13(2)	Are records being kept on appliances demanufactured in separate categories, as well as the number of each component, amount of refrigerant, etc?	\boxtimes		
Repor	118.13(3)	Are records being kept on all hazardous waste manifest and bills of lading for shipments of refrigerant, mercury switches, PCB-containing material, and kept on site for a minimum of three years?	\boxtimes		
Reportir	118.13(3)" <i>f</i> "	Are copies of annual reports (containing all the record keeping requirements) that have been sent to the Department Central Office being retained for at least three years?	\boxtimes		

	IAC 567 C	hapter 118.15: Shredding of Appliances	Yes	No	NA
ng	118.15(1)	Has fluff from shredding been tested at least quarterly for PCBs, and TCLP for heavy metals? Have these results being sent to the department within 30 days of the end of each quarter?			\boxtimes
rocessing	118.15(1)	Have the results from fluff testing been submitted to the department within 30 days of the end of each quarter? And are these records being kept on site for a minimum of three years?			\boxtimes
	118.15(3)	Are appliances being demanufactured before shredding or processing?			\boxtimes
***************************************	118.15(3)	If appliances are being accepted from demanufacturers for recycle/disposal, have the appliances been demanufactured in accordance with Federal regulations and state laws from which the appliances were received?			\boxtimes

Summary of Reminders:

1) Keep a minimum of three inches of absorbent material in the bottom of PCB storage containers.

Inspector: Bert Noll

Date: 11/16/22

Reviewer: Ryan Stouder

Date: 11/17/2022 Ryan Stand