

November 8, 2023

Mr. Mick Leat
IDNR – Land Quality Bureau
Wallace State Office Building
502 E. 9th Street
Des Moines, IA 50319



Re: Biennial Survey Monument Inspection
South Central Iowa Solid Waste Agency Landfill
IDNR Permit # 63-SDP-02-77P

Dear Mr. Leat,

In accordance with IAC 567-113.8(2)a.(5), we are submitting on behalf of the South Central Iowa Solid Waste Agency (SCISWA) the 2023 survey monument observation report for the survey monuments utilized at the SCISWA landfill. The monuments are described as 5/8" rebar and found to be undisturbed and undamaged with no significant changes to the established coordinates. The monuments were observed and locations confirmed on June 27, 2023.

The established coordinates for the Monuments are as follows:

CP 500 - N: 970.34, E: 699.67, Elev: 842.78
CP 1003 - N: 4127.14, E: 1962.95, Elev: 787.61
CP 1009 - N: 5199.82, E: 58.28, Elev: 836.71
CP 1019 - N: -679.49, E: 2825.96, Elev: 768.09
CP 1029 - N: -174.58, E: 4504.87, Elev: 749.51
CP 6012 - N: -1537.20, E: 102.98, Elev: 791.38

Please let me know if you have any questions or require any additional information.

