



TYLER HINKEL FACILITY MANAGER HARRISON COUNTY SANITARY LANDFILL 2812 HIGHWAY 30 LOGAN IA 51546

SUBJECT: Harrison County Sanitary Landfill

Appliance Demanufacturing Permit Inspection

Permit # 43-ADP-01-05 Logan, Harrison County, Iowa Staff Action # 172863

Dear Mr. Hinkel:

Enclosed please find a copy of the report resulting from my appliance demanufacturing permit inspection of Harrison County Sanitary Landfill in Logan, Iowa. The report should be self-explanatory.

If you have any questions, please contact me at 712-223-8048 or by email at john.baker@dnr.iowa.gov.

Sincerely,

John Baker

Environmental Specialist

Field Services & Compliance Bureau

Logan012424.sw.HarrisonCounty.ADPCoverLetter.baker

Enc: Iowa DNR ADP Inspection Form

CC: Becky Jolly, SW Section, DNR, Des Moines, Iowa (EMAIL)

Sue Johnson, SW Section, DNR, Des Moines, Iowa (EMAIL)

Facility ADP File, Harrison County

IOWA DEPARTMENT OF NATURAL RESOURCES APPLIANCE DEMANUFACTURING (ADP) PERMIT INSPECTION FORM

Permit No.: 43-ADP-01-05	County: Harrison	
Facility Name: Harrison County Sanitary Landfill	Facility Address:	
	2812 Highway 30	
Phone Number: 712-644-3093	Logan, IA 51546	
Responsible Official: Tyler Hinkel	Mailing Address:	
	2812 Highway 30	
Phone Number: 712-644-3093	Logan, IA 51546	
Person(s) Present: Tyler Hinkel		
Date of This Inspection: January 24, 2024	Date of Last Inspection: July 28, 2022	
the desired and the second state of the second	Date of East Hispootion: oaly 20, 2022	

^{*}Be advised your facility may require, due to either SIC code or onsite management practices, an NPDES General Permit #1 (Stormwater permit).

	IAC 567 CI	napter 118.4: Appliance Storage & Handling Prior to Demanufacturing	Yes	No	NA
andling	118.4(1)	Are appliances being stored to prevent capacitors, refrigerant lines, compressors, and components containing mercury from being damaged and allowing a release into the environment?	\boxtimes		
Storage & H	118.4(2)	Are appliances being handled in a way which prevents damage, cuts, or breaks in refrigerant lines, compressors, capacitors and components containing mercury from being damaged and allowing a release into the environment?	\boxtimes		
St	118.4(3)	Are less than 1,000 appliances being stored prior to demanufacturing?	\boxtimes		
	118.4(4)	Are appliances being demanufactured in 270 days or less?			

Comm	ents:	

	IAC 567 CI	napter 118.7: Fixed Facility & Mobile Operations	Yes	No	NA
perations	118.7(1)	Is demanufacturing taking place on an impervious floor (including but not limited to concrete, ceramic tile, or metal)?	\boxtimes		
Opera	118.7(2)	Is the point of demanufacturing located 50 feet or more from a well and any water of the state?	\boxtimes		
	118.7(5)	Is a unique marking system (minimum of nine inches square) being applied to the appliances after demanufacturing?	\boxtimes		

Comments: Appliances are marked with an H after demanufacturing.

5	D)	napter 118.8: Training	Yes	No	NA
inic	118.8	Is at least one owner or employee completed a Department-approved training course?	\boxtimes		
Ĥ	118.8	Is one trained person on site at all times when appliances are being demanufactured?	\boxtimes		

0-			_
co	mm	ents	

IAC 567 C	hapter 118.6: Permit Application Requirements	Yes	No	NA
118.6(8)	Is a copy of the EPA Refrigerant Recovery or Recycling Devise Acquisition Certification available onsite?			
608 CAA (CFR)	Is a copy of the EPA Refrigerant Reclaimer's Certification available onsite if reclamation (purification) is taking place at the facility?			
IAC 567 C	hapter 118.9: Refrigerant Removal Requirements	Yes	No	NA
118.9(2)	If refrigerant is removed at a location other than a permitted ADP facility, is there documentation that it was removed by a service or repair facility certified for the removal of refrigerant?	\boxtimes		
118.9(3)	Is removal of refrigerant being done in an area where the temperature of the surrounding air and that of the appliance being demanufactured is 45 degrees Fahrenheit or greater?			\boxtimes
	hapter 118.13: Record Keeping & Reporting	Yes	No	NA
118.13(2)" <i>a</i> " & 118.13(2)" <i>g</i> "	Are the number and type of refrigerant containing appliances being tracked, as well as the amount of refrigerant removed?	\boxtimes		
118.13(3)"a"	Are bills of lading being kept as to where refrigerants are being shipped for disposal?	\boxtimes		
mmonte: Th	nis facility does not do any refrigerant removal. They have from containing appli	ances	to Ou	andte

Comments: This facility does not do any refrigerant removal. They haul freon containing appliances to Quandts in Carroll IA or Scrap Central in Omaha NE.

	IAC 567 CI	napter 118.9: Refrigerant Removal Requirements	Yes	No	NA
lio	118.9(5)	If compressor oil is being removed from the refrigeration units, is it being stored in accordance with 567-119.5 (Note: AST must be large enough and on an impermeable surface to prevent spills, meet API construction standards, have absorbent material available, have a gauge to monitor liquid level, & meet Ch. 567-135 &136 if UST)			

Comments:____

	IAC 567 C	hapter 118.9: Refrigerant Removal Requirements	Yes	No	NA
	118.9(6)" <i>a</i> "	Is the ammonia gas being vented into water and is the resulting wastewater being properly disposed of?			\boxtimes
Refrigerant	118.9(6)"e"	Is sodium chromate being properly stored in DOT-approved containers labeled with a proper EPA-approved chromium label stating "chromium" or "hazardous waste"?			
Refri	118.9(6)" <i>g</i> "	Does the facility have an EPA ID number (RCRA)?			\boxtimes
Gas F	118.9(6)" <i>h</i> " & 118.9(6)" <i>i</i> "	Is asbestos insulation being removed and handled properly?			\boxtimes
mmonia	IAC 567 C	hapter 118.13: Record Keeping & Reporting	Yes	No	NA
Amm	118.13(2)"a"(Are records being kept on the number of sodium chromate–containing appliances being demanufactured			\boxtimes
	118.13(2)" <i>f</i> "	Are records being kept on the number of sodium chromate–containing appliances shipped to another demanufacturer			\boxtimes
	118.13(3)"a" 118.13(3)"b"				\boxtimes

_	
Comme	· mata ·
Comme	ints:
	iito.

	IAC 567 C	hapter 118.10: Mercury-Containing Component Removal & Disposal	Yes	No	NA
	118.10(1)	Are all components containing mercury being removed?	\boxtimes		
S	118.10(2)	Are mercury components being stored in containers with a proper EPA- approved label stating "Universal Waste-Mercury Containing Equipment", or Waste Mercury-Containing Equipment" in both English and the predominant language of any non-English-reading workers?			
omponents	118.10(3)	Is the date when the first mercury-containing component was placed in the container affixed to the container?	\boxtimes		
S	118.10(4)	Storage of mercury is limited to one year, after which, it must be transported to an EPA-approved recycler/recovery facility. Has storage been under one year?	\boxtimes		
Mercury	118.10(8)	Are fluorescent tubes, lamps, bulbs, etc., being placed in a container and packaged to prevent breakage to an EPA-approved recycler?	\boxtimes		
Me	IAC 567 C	hapter 118.13: Record Keeping & Reporting	Yes	No	NA
	118.13(2)	Are records being kept on the number of mercury-containing appliances being demanufactured, number of mercury switches removed, number of fluorescent tubes removed, as well as the number of mercury thermocouples being removed?	\boxtimes		
	118.13(3)	Are records or bills of ladings being kept on the shipment of mercury-containing components?	\boxtimes		

Comments: The mercury container was dated 08-06-23.

	IAC 567 Ch	napter 118.11: Capacitor Removal Requirements	Yes	No	NA
	118.11(4)" <i>a</i> "	Does the facility have an EPA TSCA ID number for capacitor storage (required if facility has no RCRA ID #)?	\boxtimes		
	118.11(4)" <i>b</i> "	Are PCB items being stored in a manner that provides adequate protection from the elements and adequate secondary containment? (Note: Storage must take place on an impervious material above the 100-year floodwater elevation)	\boxtimes		
ဖွ	118.11(4)"c"	Is the point of demanufacturing located above the 100-year flood water elevation?	\boxtimes		
Capacitors	118.11(4)" <i>d</i> "	Are PCB storage containers filled to two inches of absorbent material in the bottom?	\boxtimes		
Сара	118.11(4)"e"	Are PCB containers DOT-approved and labeled with a 6" by 6" yellow label stating "PCBs" as described in CFR part 761.45?	\boxtimes		
PCB	118.11(4)" <i>g</i> "	Is the storage for non leaking small PCB capacitors that do not comply with the requirements in 118.11(4) "a" to "f" stored for less than 30 days from the date of removal and a notation places on the PCB capacitor indicating the date the item was removed from the appliance?	\boxtimes		
	118.11(4)"f' & 118.11(4)"h"	Is the date when the first capacitor was placed in the storage container on the label? Storage of capacitors is limited to 270 days, after which they must be transported to an EPA-approved landfill or incinerator. This burial or incineration must be documented (within one year of the date on the container) and this record kept by the demanufacturer for three years from the date the PCB waste was accepted by the initial transporter.	\boxtimes		

	IAC 567 CH	AC 567 Chapter 118.13: Record Keeping & Reporting			
PCB Capacitors	118.13(2)	Are records being kept on the number of PCB containing appliances being demanufactured, number of PCB capacitors and ballasts as well as the date the first PCB-containing item was placed in the storage drum that is in use on December 31? number of mercury thermocouples being removed?			
	118.13(3)" <i>a</i> " & 118.13(3)" <i>b</i> "	Are records being kept on the shipment of PCB components and the documentation of destruction or receipt from a regional collection center for all PCB materials shipped?	\boxtimes		
	118.13(3)" <i>d</i> "	Are records being kept documenting inspections of the PCB storage area as required by 118.11(4)"h"?	\boxtimes		

Comments: The TSCA ID# for this facility is IAW000000600.

w	IAC 567 Chapter 118.12: Spills				NA
Spills	118.12(1)	Are spill records being kept and has the facility reported spills that resulted in a hazardous condition?			\boxtimes
	118.12(2)	Is a mercury spill kit on hand?	\boxtimes		

Comments:	
-----------	--

Reporting	IAC 567 C	hapter 118.13. Record Keeping & Reporting	Yes	No	NA
	118.13(2)	Are records being kept on appliances demanufactured in separate categories, as well as the number of each component, amount of refrigerant, etc?	\boxtimes		
	118.13(3)	Are records being kept on all hazardous waste manifest and bills of lading for shipments of refrigerant, mercury switches, PCB-containing material, and kept on site for a minimum of three years?	\boxtimes		
	118.13(3)" <i>f</i> "	Are copies of annual reports (containing all the record keeping requirements) that have been sent to the Department Central Office being retained for at least three years?	\boxtimes		

Comn	nents	:

	IAC 567 Chapter 118.15: Shredding of Appliances				NA
Processing	118.15(1)	Has fluff from shredding been tested at least quarterly for PCBs, and TCLP for heavy metals? Have these results being sent to the department within 30 days of the end of each quarter?			\boxtimes
	118.15(1)	Have the results from fluff testing been submitted to the department within 30 days of the end of each quarter? And are these records being kept on site for a minimum of three years?			\boxtimes
	118.15(3)	Are appliances being demanufactured before shredding or processing?			\boxtimes
	118.15(3)	If appliances are being accepted from demanufacturers for recycle/disposal, have the appliances been demanufactured in accordance with Federal regulations and state laws from which the appliances were received?			\boxtimes

Com	ments	:
00111		

	Summary of Recommendations:
1)	
2)	
3)	
4)	
5)	

Summary of Requirements:	Compliance Date:
1) Continue to comply with permit requirements	Ongoing
2)	
3)	
4)	
5)	

Inspector: John Baker

Date: <u>01/25/24</u>

Reviewer: Wendy Wittrock

Date: 01/25/24

Facility Photographs



Appliance Demanufacturing Area



Mercury and PCB Storage Containers



Non-Freon Appliances and Signage



Freon Containing Appliances and Signage