

mercury storage drum that is in use

on December 31.

(Not in lbs)

APPLIANCE DEMANUFACTURING ANNUAL REPORT

JANUARY 1, 2023 - DECEMBER 31, 2023

Permit Number: 21-ADP-05-06				BEFORE			
Responsible Official: Tom Clark			JAN	IUARY 31 ST			
Facility Name: City Of Spencer Transfer Station			Send completed form to:				
Address: 101 West 5th st			lowa DNR Land Quality Bureau 502 E 9 th St Des Moines, IA 50319-0034 OR FAX: 515-725-8202				
City, State Zip: Spencer, la 51301							
ATTACH ADDITIONAL PAGES IF NECESSARY.							
Are appliances containing refrigerants accepted at this facility?			′es 🔲 No				
Are appliances containing mercury accepted at this facility?			es No				
Are appliances containing sodium chromate accepted at this facility?			es 🛛 No				
Are appliances containing PCB capacitors and ballasts accepted at this facility?							
Number of Appliances Demanufactured in each category							
TYPE OF APPLIANCE NUMBER TYPE OF APPLIANCE		NCE	NUMBER				
		Furnaces		13			
Refrigerators and freezers	222	Furnaces		13			
Refrigerators and freezers Commercial coolers	0	Clothes washers and drye	rs	142			
		1	rs				
Commercial coolers	0	Clothes washers and drye	rs	142			
Commercial coolers Air-conditioning units	0 95	Clothes washers and drye Dishwashers	rs	142			
Commercial coolers Air-conditioning units Dehumidifiers	0 95 158	Clothes washers and drye Dishwashers Microwave Ovens Stoves/ Ovens	ercury,	142 84 255			
Commercial coolers Air-conditioning units Dehumidifiers	0 95 158	Clothes washers and drye Dishwashers Microwave Ovens Stoves/ Ovens or Other items containing M	ercury,	142 84 255			
Commercial coolers Air-conditioning units Dehumidifiers	0 95 158 13	Clothes washers and drye Dishwashers Microwave Ovens Stoves/ Ovens or Other items containing M	ercury, ning articles.	142 84 255 77			

Component Removal						
TYPE OF COMPONENT	NUMBER	TYPE OF COMPONENT	NUMBER			
Number of mercury switches removed. (Not in lbs)	0	Amount of Refrigerant Removed	332			
Number of mercury thermocouples removed. (Not in lbs)	0	Number of PCB capacitors removed. (Not in lbs)	213			
Number of fluorescent tubes removed.	0	Number of PCB ballasts removed.	7.4			

December 31.

(Not in lbs)

in the storage drum that is in use on

Sodium Chromate Appliances			
Number of sodium chromate containing appliances shipped to another demanufacturer	0		

Questions? Call or email: Susan Johnson, susan.johnson@dnr.iowa.gov, 515-217-0872 Please mail completed form to: Land Quality Bureau, 502 E 9th St, Des Moines IA 50319 04/2021 cmc

stored

74

Certification

I certify under penalty of law that I am the owner, operator, or authorized representative of the owner or operator and that I have examined and am familiar with the information reported above, and that I believe the information is true, accurate and complete.

Name & Agency of Per	son Certifying (please type or print) Th	omas Clark		
Telephone Number:	712-580-7270	Fax Number:	712-580-7176	
Email: tclark@spence	riowacity.com			
Signature:	ion I Clah	Date:	1-16-2024	
-		 :		
Additional Comments:				

In accordance with Iowa Administrative Code 567 Chapter 118.13(1) – Annual reports with the information required in subrule 118.13(2) are due January 31 each year for the activities of the previous calendar year shall be retained at the facility for at least three years.