

DIRECTOR KAYLA LYON

Fax: 515-725-8202

April 18, 2024

METRO WASTE AUTHORITY
METRO PARK EAST LANDFILL
12181 12TH AVENUE NE
MITCHELLVILLE IA 50169-9802

Re: Metro Park West Landfill

Boone and Greene County Municipal Solid Waste Landfill Units

Permit #08-SDP-03-84

2023 Annual Water Quality Report, Leachate Control System Performance Evaluation Report, and Landfill Gas Report (<u>Document No. 109105</u>)

Dear Mr. McCoy:

The Iowa Department of Natural Resources (DNR) reviewed the 2023 Annual Water Quality Report, Leachate Control System Performance Evaluation Report, and Landfill Gas Report, dated January 31, 2024, as submitted by HDR. The DNR has the following comments:

Report Priority

No request was made.

Sampling Summary

Phone: 515-725-8200

Hydrologic monitoring at the site shall be conducted in accordance with the Hydrologic Monitoring System Plan in Appendix 4 of the 2021 Permit Renewal Application, dated June 14, 2021, and the Proposed Monitoring Network Updates, dated October 18, 2022, both as submitted by HDR. The DNR has the following comments:

- 1. Background monitoring points are MW-5AR (Boone County MSWLF Unit), and MW-6A and MW-28 (Greene County MSWLF Unit).
- 2. Detection monitoring points are MW-1, MW-2AR, MW-9B, MW-12, MW-17, MW-18 and MW-26. In addition, the permit requires monitoring of the Raccoon River twice per year for arsenic.
- 3. Monitoring well MW-6A has historically had "J-flagged" detections of volatile organic compounds and the DNR comment letter dated February 13, 2023 (<u>Document No. 105838</u>), recommended checking for the presence of methane in the well and if present consider installing another background well. HDR responded in a letter dated March 1, 2023 (<u>Document No. 105984</u>), that MWA will conduct methane monitoring at monitoring well MW-6A during the quarterly methane monitoring events in 2023." However, the results were not included in the report. Please provide the results.

4. Clarify the location of sampling point MPWRAC0004 as the table in Appendix H indicates "STAKED" and "LOST GPS."

Monitoring Well Maintenance and Performance Reevaluation

No comments.

Leachate Control System Performance Evaluation Report

Table 12 Leachate Management Summary indicates that leachate head data was not collected during portions of the year. Further, it was noted that leachate recirculation occurred in August, September, and October 2023. This appears to not comply with permit special provision X.5.h. and the Iowa Administrative Code 567 113.7(5)b.(3&14). Please provide the results or a schedule to resume leachate head monitoring. Meanwhile, recirculation is not allowed until this issue is resolved.

Landfill Gas Annual Report

No comments.

Please respond as noted above **on or before May 18, 2024**. If you have any questions, please contact me at (515) 229-8356 or mike.smith@dnr.iowa.gov.

Sincerely,

Michael W. Smith, P.E. Environmental Engineer Senior Land Quality Bureau

copy: Katie Kinley, P.E.

HDR Engineering, Inc. 1917 S 67th Street Omaha, NE 68106-2973 DNR Field Office #5