

July 19, 2024

SCOTT AREA SANITARY LANDFILL ATTN BRYCE STALCUP DIRECTOR 11555 110<sup>TH</sup> AVENUE DAVENPORT IA 52804

RE: Compliance Inspection SDP Permit No. 82-SDP-09-72P; Scott County, Iowa

Dear Mr. Stalcup:

On June 26, 2024 I met with you to conduct a compliance inspection of the Scott Area Sanitary Landfill. Attached you will find an inspection report including observations made during my visit. Based on the observations made during the compliance evaluation, there did not appear to be any landfill permitting or recordkeeping violations.

If you have any questions or would like further explanation of any part of this report, please contact me at this office at 319-653-2135 or via email <a href="mailto:ryan.stouder@dnr.iowa.gov">ryan.stouder@dnr.iowa.gov</a>.

Sincerely,

FIELD SERVICES & COMPLIANCE BUREAU

Ryan Stouder

**Environmental Specialist Senior** 

Encl. SDP Insp Report

Phone: 319-653-2135

N:Rstoude\SW 2024\Scott County SDP Insp 062624 N:FO6\PICTURES\2024\June\Scott County Landfill 062624

xc: Becky Jolly, IDNR Solid Waste Section, via email FOCD – Scott County SDP Landfill

www.lowaDNR.gov

Fax: 319-653-2856

					Sanitary Disposal					ES		
Perm	it #: 82-			Arran Arraig		1 3 3 1 3						Page 1
		Facil		<b>ie:</b> Scott <b>ty:</b> Scott	Area Sanitary Landfill			Date	Last li	nspecti	on:	08/17/2023
	Fa		Addres		Seals - Operations Manag 5 110 <sup>th</sup> Ave, Davenport, IA 381-1300		4	Date	This l	nspecti	on:	06/26/2024
	Resp	onsibl	Addres	ss: 1155	e Stalcup, Director 5 110 <sup>th</sup> Ave, Davenport, I <i>A</i> 381-1300	528	04		Wast	e Amou	ınt:	N/A
	••••				At the Time of					_		
			·		ce Stalcup	•	am	bient	temper	rature: 8	33°F,	•
• a	ctive ur	nit(s):	Cell #8 a		e over Cell #1/2	•						INW, 7-9 MPH
				N/A – no	npliance was being achieved; t applicable or not observed; F	NO – ND –	compii - previc	ance w ously no	as not b oted defi	eing acn ciency (F	PND).	
					I. Documents and	l Rec						
Yes	No	N/A	PND	1 Dormit	Item //Amendment documents	-	Yes 🖂	No_	N/A	PND	Fina	Item ncial assurance
$\boxtimes$	H		-H		ploration report	-		-	<u> </u>			rm water permit
$\boxtimes$					Specs and QC&A Reports	] [	$\boxtimes$				1. SV	/A/SWAC documentation
×					screening inspection records							erator Certification
$\boxtimes$		H			ate recirculation authorization onitoring/remediation results	4 }			╏		3. DC 4. ER	
岗	H	十一	H		dwater monitoring results	-	Ä	Н	$\exists$		5. Oth	
					e/Postclosure plans/results							
					II. Operating	j Pro		· T · · · · · · · · · · · · · · · · · ·	T			
Yes	No 1	N/A	PND	1 All wor	Item ather access road to facility		Yes	No □	N/A   ⊠	PND	10 9	Item Scavenging and Salvaging
$\boxtimes$	<u>L</u>				lled Access at facility		H			H		avenging and Salvaging
$\boxtimes$					or other perimeter barriers				$\boxtimes$			alvaging authorized
$\boxtimes$				b. entrand	ce gate with lock				$\boxtimes$		c. sa	lvaged material orderly
$\boxtimes$				c. safe/pr	oper on-site traffic patterns				$\boxtimes$		d. sa	ilvage removal adequate
$\boxtimes$				3. Signag	е				$\boxtimes$		11. /	Animal feeding and grazing
$\boxtimes$				a. facility	name and permit number				$\boxtimes$		a. ar	nimal feeding prohibited
$\boxtimes$				b. days a	nd hours of operation				$\boxtimes$		b. gr	azing on final cover limited
$\boxtimes$				c. wastes	accepted/not accepted						mon	Survey controls and uments
$\boxtimes$				d. telepho	one # of resp. official		$\boxtimes$					cility and waste boundaries eyed and marked
$\boxtimes$				4. All wea	ther access road in facility		$\boxtimes$				b. su	ırvey monuments established
$\boxtimes$				5. Adequa	ate vehicle queuing		$\boxtimes$				c. st	akes clearly marked
$\boxtimes$				6. Certifie	d scale used		$\boxtimes$				13. I	Fill Sequencing
$\boxtimes$				7. Waste	Screening		$\boxtimes$				a. lir	er system protected
$\boxtimes$				a. randon	n inspections performed		$\boxtimes$				b. sl	ope failure controlled
$\boxtimes$				b. inspect	tion records		$\boxtimes$				c. di	fferential settlement controlled
$\boxtimes$					personnel		$\boxtimes$				d. ru	n-on and runoff controlled
$\boxtimes$					otification procedures		$\boxtimes$					Control of Workface
$\boxtimes$					ited materials listing	_	$\boxtimes$					ze of area controlled
					Burning and Fire Hazards	-						ope is stable
				="	urning prohibited							ter control devices used
	_				fueling prohibited within 50							
$\boxtimes$				feet of wo			$\boxtimes$				d. ve	ectors controlled

e. operator at workface

$\boxtimes$			15. Special Waste Handling		$\boxtimes$		23. Run-on/Runoff Control Systems
$\boxtimes$			a. operator familiar with SWAC		$\boxtimes$		a. ponding controlled
$\boxtimes$			16. Waste Fill Cover		$\boxtimes$		b. dikes, ditches, berms & terraces intact
$\boxtimes$			a. daily cover adequate		$\boxtimes$		c. tile lines maintained
			b. alternative cover authorized		$\boxtimes$		24. Landfill Equipment
$\boxtimes$			c. scarification of daily cover		$\boxtimes$		a. working properly
$\boxtimes$			d. intermediate cover adequate (30/180 day)		$\boxtimes$		b. backup equipment available
$\boxtimes$			e. final cover maintained		$\boxtimes$		25. Groundwater Monitoring Wells
$\boxtimes$			17. Leachate seeps		$\boxtimes$		a. wells intact
$\boxtimes$			a. seeps identified and controlled		$\boxtimes$		b. caps and locks
$\boxtimes$			18. Leachate recirculation		$\boxtimes$		26. Gas Monitoring Wells/Points
$\boxtimes$			a. composite liner		$\boxtimes$		27. Emergency Procedures
$\boxtimes$			b. RD&D authorization		$\boxtimes$		a. ERRAP available to staff
$\boxtimes$			c. personnel protected		$\boxtimes$		b. emergency numbers posted
$\boxtimes$			d. erosion controlled		$\boxtimes$		28. Final Cover System
$\boxtimes$			e. vegetation maintained		$\boxtimes$		a. final cover over completed areas
$\boxtimes$			19. Site Litter Control		$\boxtimes$		b. seeded
$\boxtimes$			a. on-site litter picked up daily		$\boxtimes$		c. vegetation established
$\boxtimes$			b. offsite litter picked up daily		$\boxtimes$		d. run-on, runoff, and ponding
							controlled e. differential settlement
$\boxtimes$			c. record of why litter not picked up				controlled
$\boxtimes$			20. Dust Control			$\boxtimes$	29. Other
$\boxtimes$			a. dust controlled as vehicles enter/exit facility				
$\boxtimes$			b. dust controlled on internal roads				
$\boxtimes$			c. dust controlled at the workface				
$\boxtimes$			21. Mud Control				
$\boxtimes$			a. mud controlled as vehicles enter/exit facility				
$\boxtimes$			22. Leachate Control and Treatment				
$\boxtimes$			a. system operational				
$\boxtimes$			b. head measurement device				
$\boxtimes$			c. seeps controlled				
$\boxtimes$			d. leachate tank maintained				
$\boxtimes$			e. leachate lagoon maintained				
$\boxtimes$			f. POTW agreement				
$\boxtimes$			g. sanitary sewer discharge				
$\boxtimes$			h. NPDES discharge permit				
$\boxtimes$			i. NPDES on-site treatment				
Comr	ments:			l.			

On June 26, 2024 Bryce Stalcup and I discussed the landfill permitting requirements and current operations. The documents requested as listed in Table 1 above were available and we discussed their compliance efforts. Many of the documents were organized binders that contained the current permit along with the permit amendments, special waste authorizations etc. Many of the landfill records were available in an electronic format.

All of the landfill operators are cross trained for insuring the understanding of the landfill operations. I was able to review waste load screens, which is based upon random waste loads. Any prohibited materials are identified by personnel, pulled from the load or at the working face and placed in appropriate locations. We discussed the two scale options, one for average residential hauler and the other for routine commercial haulers. The flow pattern of the waste hauling is well defined for ensuring efficiency, utilizing signage and all-weather roadway. Special waste collection is located on the west side of the landfill for waste tires, clean construction wood, shingles and currently tree material due to the compost facility impacts by the Mississippi River flooding.

The landfill gases are collected and flared, but an effort is being made to generate energy from the landfill gases in the future. Recent rain event delivered 2.5 inches of water, so the area is moist. Waste haulers run over cattle grades to reduce mud being tracked through the haul roads on site.

Daily cover utilizes soil, automotive fluff and tarps, which are staged for the day. A fair amount of auto fluff is available for the initial lift of the new Cell 9. The current working face is utilizing a flat filling effort and the area was appropriately sized part of Cell 8 and over Cells 1 & 2. At the time auto fluff was being used as daily cover although tarps are also used. All areas of the Cells' working face were covered with a uniform layer of soil/auto fluff. The litter was minimal in the areas that I observed and routine pickers are utilized to clean the area. We visited the central leachate collection system and controls, where two - 2 million-gallon recirculating lagoons are used to treat the leachate from the landfill operations. Leachate evaporation effects are being utilized to reduce the amount of leachate to be hauled to the Davenport Wastewater Pollution Control for further treatment.

In general, the landfill appears to be well managed and in compliance with its' permit as well as the operating procedures outlined in 567 IAC 113.

INSPECTOR	1.54	Date:
	Ryan Stouder Environmental Specialist Senior	07/19/2024
REVIEWER	Tom	7/22/2024