



HALL ENGINEERING COMPANY

Consulting Engineers
Since 1903

PO Box 825
Alliant Building · Suite 101
300 Sheridan Avenue
Centerville, IA 52544
641.437.4477 · Fax 641-437-4479


October 14, 2024

| | | |
|-----|--|---|
| To: | Iowa Department of Natural Resources Field Office No. 5 Attn: Ted Petersen, Supervisor Wallace State Office Bldg. 502 E. 9 th Street Des Moines, IA 50319-0034 | Iowa Department of Natural Resources Solid Waste Section Attn: Mike Smith Wallace State Office Bldg. 502 E. 9 th Street Des Moines, IA 50319-0034 |
|-----|--|---|

ENGINEER'S REPORT

APPANOOSE COUNTY SANITARY LANDFILL
26260 195th Avenue
Appanoose County, Iowa

CLOSURE PERMIT NO. 04-SDP-01-76C



I hereby certify that this engineering document was prepared by me or under my direct personal supervision and that I am a duly licensed Professional Engineer under the laws of the State of Iowa.

Nancy J. Buss
Nancy J. Buss, P.E.
License number 18186

10/14/2024
Date

My license renewal date is December 31, 2024.
Pages or sheets covered by this seal:

Pages covered by this certification:
Pages 1 and 2

Copy: Dane Blozovich, Director
Rathbun Area Solid Waste Commission

ENGINEER'S REPORT

APPANOOSE COUNTY SANITARY LANDFILL

CLOSURE PERMIT NO. 04-SDP-01-76C

This is to certify that a semi-annual inspection of the North Unit and a biennial inspection of the South Unit of the Appanoose County Sanitary Landfill was made by me or under my direct personal supervision on October 11, 2024 in conformance with referenced Closure Permit. Based upon that inspection, the landfill site was found to be in substantial compliance with the permit requirements and the approved closure plans.

The North Unit continues to be monitored for water quality in accordance with the approved HMSP, and Special Provision 4 of Revised Closure Permit, Document Number 11604, August 30, 2024.

Site Maintenance Comments and Recommendations

The Indian Hills Community College (IHCC) Sustainable Agriculture Program continues to provide landfill site maintenance work.

North Unit: The new background monitoring well (MW-60) has been installed.

South Unit: The low water crossing between the landfill North Unit and South Unit is passable.