



HALL ENGINEERING COMPANY

Consulting Engineers
Since 1903

PO Box 825
Alliant Building · Suite 101
300 Sheridan Avenue
Centerville, IA 52544
641.437.4477 · Fax 641-437-4479


October 24, 2025

To: Iowa Department of Natural Resources Iowa Department of Natural Resources
Attn: Ted Petersen, Supervisor Land Quality Bureau
Wallace State Office Bldg. Attn: Chad Stobbe, Environmental Specialist
502 E. 9th Street 502 E. 9th Street
Des Moines, Iowa 50319-0034 Des Moines, Iowa 50319-0034

ANNUAL ENGINEER'S REPORT

RATHBUN AREA SOLID WASTE COMMISSION
TRANSFER STATION
3020 McCarty St.
Centerville, Iowa

PERMIT NO. 04-SDP-09-05P-XFR



I hereby certify that this engineering document was prepared by me or under my direct personal supervision and that I am a duly licensed Professional Engineer under the laws of the State of Iowa.

Nancy J. Buss
Nancy J. Buss, P.E.
License number 18186

10/24/2025
Date

My license renewal date is December 31, 2026.
Pages or sheets covered by this seal:

Pages covered by this certification:
Pages 1 and 2

Copy: Dane Blozovich, Director
Rathbun Area Solid Waste Commission

ANNUAL ENGINEER'S REPORT

RATHBUN AREA SOLID WASTE COMMISSION TRANSFER STATION

PERMIT NO. 04-SDP-09-05P-XFR

This is to certify that an annual inspection of the Rathbun Area Solid Waste Commission Transfer Station was made by me or under my direct personal supervision on October 23, 2025 in conformance with referenced Permit and Iowa Administrative Code 567 Chapter 106.14(2)

Based upon the inspection of the facility, inspection of the Transfer Station documents, and an interview with the Operator, the Transfer Station is in compliance with the applicable Sections of Chapter 106.10, 106.11, 106.12, 106.13, 106.14, 106.15, 106.16, and 106.18 as of the date of this Report.