

Sent Via Electronic Mail
Receipt Confirmation Requested

August 27, 2026

MICHAEL MCCOY
METRO WASTE AUTHORITY
300 EAST LOCUST STREET, SUITE 100
DES MOINES, IA 50309-1996
mmc@mwatoday.com

RE: Sanitary Disposal Project Site Visit
Metro Park West Landfill, 20 335th St., Perry, IA
Sanitary Disposal Project Permit No. 08-SDP-03-84P-MLF

Mr. McCoy:

Enclosed is the report completed by Malia Schepers during the inspection of your facility near Perry on August 25, 2026. A copy was left on-site at that time.

The report should be self-explanatory. The sediment pond should be cleaned out as soon as possible.

You may contact Malia Schepers (515-250-1097; malia.schepers@dnr.iowa.gov) or this office with any questions or comments.

Sincerely,



Digitally signed by Bill Gross
Date: 2026.08.27 11:52:44 -05'00'

Bill Gross
Environmental Specialist Senior, Field Office #5
515-238-7871

c: [Mike Smith](#) & [Becky Jolly](#), Land Quality Bureau, Iowa DNR (w/encl.)

IOWA DEPARTMENT OF NATURAL RESOURCES

Field Office 5

6200 Park Avenue, Suite 200, Des Moines, IA 50321

515-725-0268

Sanitary Disposal Project Visit

Permit #: 08-SDP-03-84P-MIF Date this Inspection: 8-25-26 Previous Inspection Date: 1-27-26

Facility Name: Metro West, Perry Weather Conditions at Time of Visit: Cloudy 67° Dry

Person(s) Contacted: Willy Barrow 515-210-4038

Were deficiencies noted or significant observations made during this inspection?

Yes – See Comments Sec., No – No deficiencies noted, Blank – Not applicable or observed, PND – Previously Noted Deficiency

Observations

Yes	No	PND	Item	Yes	No	PND	Item
☐	☒	☐	1. Fill Cover: daily; intermediate; final	☐	☒	☐	10. Special Waste Handling
☐	☒	☐	2. Control of Face: slope; width; location	☐	☒	☐	11. Recycling Activities
☐	☒	☐	3. Compaction	☐	☒	☐	12. Operator Certification
☐	☒	☐	4. Cover erosion; Ponding	☐	☒	☐	13. Staffing
☐	☒	☐	5. Drainage into fill	☐	☒	☐	14. Equipment Backup/Maintenance
☐	☒	☐	6. Leachate Mgmt. & Control	☐	☒	☐	15. Interior Roads
☐	☒	☐	7. Litter	☐	☒	☐	16. Perimeter fence, gate, signs
☐	☒	☐	8. Wet Weather Area	☐	☒	☐	17. Photos taken
☐	☒	☐	9. Construction & Demolition Area	☐	☒	☐	18. Follow-up needed

Location of Work Face: Cell C

Comments: - Waste is currently going in Cell C

- the south side of Cell D is covered w/ intermediate cover and seeded - a berm has been added to slow erosion - top half still bare - was just recently seeded

- clay liner is currently being installed in the new cell -

- the new leachate basin liner has been installed along w/ new sediment basin

the old sediment basin is full of sediment and has not

Follow-up Actions Needed: been cleaned out yet. Reported the the construction company will be cleaning it out after cell is finished

AUTHENTICATION

INSPECTOR:

Maria Schepers

FACILITY CONTACT:

Willy Barrow