



HALL ENGINEERING COMPANY

Consulting Engineers
Since 1903

PO Box 825
Alliant Building · Suite 101
300 Sheridan Avenue
Centerville, IA 52544
641.437.4477 · Fax 641-437-4479


October 19, 2026

To:	Iowa Department of Natural Resources Field Office No. 5 Attn: Ted Petersen, Supervisor Wallace State Office Bldg. 502 E. 9 th Street Des Moines, IA 50319-0034	Iowa Department of Natural Resources Solid Waste Section Attn: Mike Smith Wallace State Office Bldg. 502 E. 9 th Street Des Moines, IA 50319-0034
-----	--	---

ENGINEER'S REPORT

APPANOOSE COUNTY SANITARY LANDFILL
26260 195th Avenue
Appanoose County, Iowa

CLOSURE PERMIT NO. 04-SDP-01-76C



I hereby certify that this engineering document was prepared by me or under my direct personal supervision and that I am a duly licensed Professional Engineer under the laws of the State of Iowa.

Nancy J. Buss

Nancy J. Buss, P.E.
License number 18186

10/19/2026

Date

My license renewal date is December 31, 2026.
Pages or sheets covered by this seal:

Pages covered by this certification:
Pages 1 and 2

Copy: Dane Blozovich, Director
Rathbun Area Solid Waste Commission

ENGINEER'S REPORT

APPANOOSE COUNTY SANITARY LANDFILL

CLOSURE PERMIT NO. 04-SDP-01-76C

This is to certify that the semi-annual inspection of the North Unit and the annual inspection of the South Unit of the Appanoose County Sanitary Landfill was made by me or under my direct personal supervision on October 16, 2026 in conformance with referenced Closure Permit. Based upon that inspection, the landfill site was found to be in substantial compliance with the permit requirements and the approved closure plans.

The North Unit continues to be monitored for water quality in accordance with the approved HMSP, and Special Provision 4 of the 10th Revised Closure Permit issued on November 5, 2025.

The Indian Hills Community College (IHCC) Sustainable Agriculture Program continues to provide landfill site maintenance work.

Site Maintenance Comments and Recommendations

North Unit:

Cottonwood Tree and Red Cedar Tree saplings are beginning to grow along the drainage outlets.

South Unit:

None